

APPENDIX B-Page 1 of 6 Tel: +886 2 26099301 Fax: +886 2 26099303

B.1 Conducted Emission Measurement



FRONT VIEW



BACK VIEW



Audix Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX B-Page 2 of 6 Tel: +886 2 26099301 Fax: +886 2 26099303

Partner System








APPENDIX B-Page 3 of 6 Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 Radiated Measurement at Chamber

Frequency Below to 1GHz



FRONT VIEW



BACK VIEW



Audix Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX B-Page 4 of 6 Tel: +886 2 26099301 Fax: +886 2 26099303

Above to 1 ~ 18GHz



FRONT VIEW




BACK VIEW



APPENDIX B-Page 5 of 6 Tel: +886 2 26099301 Fax: +886 2 26099303

Above to 18 ~ 40GHz



File Number: C1M1809237

Report Number: EM-F180514, EM-F180515

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX B-Page 6 of 6 Tel: +886 2 26099301 Fax: +886 2 26099303

B.3 RF Conducted Measurement



Report Number: EM-F180514, EM-F180515

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.