



1132 West 1700 North t.435.753.1881 js@junipersys.com
Logan, UT 84321 USA f.435.753.1896 www.junipersys.com

Subject : Request to change in Identification.

Dear Regulatory Authority,

This Change of Identification request applies for a new FCC ID: as established in 47CFR 2.933(b) for a currently approved device. This application by Juniper Systems, Inc. will establish a new FCC ID: VSF22455 under Juniper Systems, Inc. grantee code for purpose of marketing. The original grant to Original Applicant will remain in effect.

Per 2.933(b)

1. The original identification is AU792U05E06800
2. The original grant date is 08/18/2005
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter
External Photos
FCC ID label format and location

Sincerely,

Kent Campbell
Product Assurance Manager
Juniper Systems, Inc.