

**From:** LEE,Kyung-Taek [klee@ltaab.com]  
**Sent:** Monday, February 11, 2008 7:25 PM  
**To:** 'TIMCO TCB'  
**Cc:** LTA(CHAhn)  
**Subject:** RE: ATID CO., LTD - FCC ID: VUJAT570W  
Hello,

Thank you for your reply.

The FCCID of device which supports the GSM module is 'VUJAT570'. This device have GSM Module and WLAN module. I uploaded the documents to Timco. and Timco submitted it to FCC.

Timco Job number of the FCC ID: VUJAT570 is 51KC8 and 52KC8.

This project is very urgent. please check it as soon as possible.

Best Regards,  
K.T. LEE

---

**From:** TIMCO TCB [mailto:tei@timcoengr.com]  
**Sent:** Tuesday, February 12, 2008 4:30 AM  
**To:** klee@ltaab.com  
**Subject:** ATID CO., LTD - FCC ID: VUJAT570W

Hello,

Thank you for your reply and revised exhibits. Concerning your reply to question 1., please specify the FCCID of the product (industrial PDA) which supports the GSM module. It must be clear that FCCID VUJAT570W does not support GSM functions.

Best Regards,

TIMCO Engineering Inc.

---

**From:** LEE,Kyung-Taek [klee@ltaab.com]  
**Sent:** Friday, February 08, 2008 8:27 PM  
**To:** 'TEI'  
**Cc:** chahn@ltaab.com  
**Subject:** RE: ATID CO., LTD - FCC ID: VUJAT570W  
Hello,

Thank you for your help.

1. This device is not capable of VoIP. It have a option for GSM Module. When the option of GSM Module was included in this device, It is used only by Phone.
- 2.This device was finished the procedure for equipment authorization(FCC DoC). It is recorded in cover letter.
3. OK. I retested for power. and I revised the test report and 731 form.

Best Regards,  
K.T. LEE

---

**From:** TEI [mailto:tei@timcoengr.com]  
**Sent:** Saturday, February 09, 2008 4:57 AM  
**To:** ktleel@litalab.com; chahn@litalab.com  
**Subject:** ATID CO., LTD - FCC ID: VUJAT570W

## TIMCO ENGINEERING INC.

849 NW State Road 45  
Newberry, Florida 32669  
<http://www.timcoengr.com>

888.472.2424 F 352.472.2030 email: [tei@timcoengr.com](mailto:tei@timcoengr.com)

## TCB & FCB

*FCC Approvals  
Industry Canada Approvals  
Notified Body for Europe*

Resend 2/8/08, 2/1/2008

MR. K. T. LEE  
LTA CO., LTD.  
+82-31-323-6008 +82-31-323-6010  
ktleel@litalab.com; chahn@litalab.com

SUBJECT: ATID CO., LTD - FCC ID: VUJAT570W

REFERENCE: JOB 219KC8

Dear MR. LEE:

**This application is on hold until these questions are resolved.** Please answer all question(s) together and only respond to [tei@timcoengr.com](mailto:tei@timcoengr.com). Any other method will cause **unnecessary delay.**

**DO NOT HIT REPLY!** Your response should be sent **ONLY** to [tei@timcoengr.com](mailto:tei@timcoengr.com). Any additional exhibits that are sent should be **UPLOADED** at our web site – please do not attach files to your email. Responses should also contain the job number, applicant name and FCC ID of the device. If an acceptable response is not received within 2 weeks the job will be closed & there will be additional charges to reopen.

**Answer all questions.** Be sure to number or identify your answer with the corresponding question. If you are referring to another document, be sure to give the page number and paragraph reference where your response can be found.

**We are sorry for this new letter. Based upon our final review of this application we have the following questions:**

1. **RF exposure:** This device appears to be capable of VoIP. It has a microphone and speaker for voice operation. Please explain. Alternatively, please provide SAR evaluation for held-to-ear operating configuration.
2. **Computer peripheral:** This device is also considered a class B computer peripheral. No information was found as to whether it was subject to the DoC or Certification procedure. Also, the label does not show any info about the DoC logo. Please include a statement of compliance in the test report or separate cover letter. The statement should describe whether the device was tested for compliance with part 15B, whether it complies, and which procedure was used for equipment authorization (DoC or Certification under JBP)
3. **Output power:** Please confirm whether the output power (80mW) was re-measured and what is the re-measured value. Please revise test report with that information.

Sincerely,

Timco Engineering, Inc.