



INTERTEK TESTING SERVICES

Report No.: HK10041148-1
Sample No.: 1/3



Date: 5.MAY.2010 14:57:23



Date: 5.MAY.2010 14:59:26

Bandedge Plot – Pursuant to FCC Part 15 Section 15.249 Requirement (Pass)