

Company Letterhead

Date: Dec. 02, 2010

Timco Engineering, Inc.
849 NW State Road 45
P.O. Box 370
Newberry, Florida 32669

Re.: Statement of the change in support unit

The EUT is Signal Booster (LP-9181A) and AP Router (LP-8616C)
New support unit: LP-8616C, FCC ID is VYTLP-8616C

To Whom It May Concern:

Loopcomm Technology, Ltd. is marketing under New support unit, original support unit: AP Router (LP-8616), FCC ID is VYTLP-8616 with EUT(Signal Booster, LP-9181A) granted on Sep. 07, 2010. The equipment marketed differs from the original one in support unit. Their circuit and performance are the same, difference is external and control chip, so we do some test in 30MHz to 1GHz, the part of RF are same.

Sincerely yours,



(signature)