

Date: November 20, 2014

Applicant: Loopcomm Technology, Inc.
FCC ID: VYTLP2596K
Correspondence Reference Number: 187271
Form 731 number: TC730034

Cover Letter

- Exhibit A LOOPCOMM_FCCID_VYTLP2596K_Attestation_Letter
Attestation Letter dated Nov. 12, 2014 from Grantee Loopcomm Technology that the product can only operate in frequency band 4 (5.725 – 5.850 GHz).
- Exhibit B LOOPCOMM_FCCID_VYTLP2596K_Software_Firmware_Change
Change of software/firmware to version 1.1.5.1 where the regulatory domain and the DFS control feature have been removed. No user configuration capability exists.
- Exhibit C LOOPCOMM_FCCID_VYTLP2596K_Operation_Description_Software_Security_20141112
Software security requirements for 2596K device.
- Exhibit D LOOPCOMM_FCCID_VYTLP2596K_TCB_letter
Explanation letter from TCB Eurofins Product Service.
- Exhibit E LOOPCOMM_FCCID_VYTLP2596K_Grantee_Confirmation_Letter
Confirmation letter from the applicant LOOPCOMM (grantee) that those Exhibits A-D have been send as a copy to Jane Lee at LOOPCOMM who is working on the enforcement action.