


APPENDIX C: Test setup photos

- Test configuration for Field Strength measurement at OATS #1



- Test configuration for Field Strength measurement at OATS #2



- Set-up for Orthogonal X



- Set-up for Orthogonal Y



- Set-up for Orthogonal Z

