







Report No.: TMWK2405001684KR




Report No.: TMWK2405001684KR


802.11ac 40MHz Chain0 5190MHz




802.11ac 40MHz Chain0 5755MHz



802.11ac 40MHz Chain0 5230MHz




802.11ac 40MHz Chain0 5795MHz




Report No.: TMWK2405001684KR


802.11ac 40MHz Chain1 5190MHz




802.11ac 40MHz Chain1 5755MHz



802.11ac 40MHz Chain1 5230MHz




802.11ac 40MHz Chain1 5795MHz




Report No.: TMWK2405001684KR

802.11ac 80MHz Chain0 5210MHz



802.11ac 80MHz Chain1 5210MHz







802.11ac 80MHz Chain0 5775MHz



802.11ac 80MHz Chain1 5775MHz



Report No.: TMWK2405001684KR



Report No.: TMWK2405001684KR


802.11ax 20MHz Chain1 5180MHz




802.11ax 20MHz Chain1 5745MHz




802.11ax 20MHz Chain1 5220MHz




802.11ax 20MHz Chain1 5785MHz



802.11ax 20MHz Chain1 5240MHz




802.11ax 20MHz Chain1 5825MHz




Report No.: TMWK2405001684KR


802.11ax 40MHz Chain0 5190MHz




802.11ax 40MHz Chain0 5755MHz



802.11ax 40MHz Chain0 5230MHz




802.11ax 40MHz Chain0 5795MHz




Report No.: TMWK2405001684KR


802.11ax 40MHz Chain1 5190MHz




802.11ax 40MHz Chain1 5755MHz



802.11ax 40MHz Chain1 5230MHz




802.11ax 40MHz Chain1 5795MHz





Report No.: TMWK2405001684KR

802.11ax 80MHz Chain0 5210MHz



802.11ax 80MHz Chain1 5210MHz



802.11ax 80MHz Chain0 5775MHz




802.11ax 80MHz Chain1 5775MHz




Report No.: TMWK2405001684KR

## Update:


802.11a 20MHz Chain0 5260MHz




802.11a 20MHz Chain0 5500MHz




802.11a 20MHz Chain0 5300MHz




802.11a 20MHz Chain0 5580MHz



802.11a 20MHz Chain0 5320MHz




802.11a 20MHz Chain0 5700MHz




Report No.: TMWK2405001684KR


802.11a 20MHz Chain0 5720MHz UNII 2C




802.11a 20MHz Chain1 5260MHz




802.11a 20MHz Chain0 5720MHz UNII 3



802.11a 20MHz Chain1 5300MHz




802.11a 20MHz Chain1 5320MHz




Report No.: TMWK2405001684KR


802.11a 20MHz Chain1 5500MHz




802.11a 20MHz Chain1 5720MHz UNII 2C




802.11a 20MHz Chain1 5580MHz



802.11a 20MHz Chain1 5720MHz UNII 3




802.11a 20MHz Chain1 5700MHz




Report No.: TMWK2405001684KR


802.11n 20MHz Chain0 5260MHz




802.11n 20MHz Chain0 5500MHz




802.11n 20MHz Chain0 5300MHz



802.11n 20MHz Chain0 5580MHz



802.11n 20MHz Chain0 5320MHz



802.11n 20MHz Chain0 5700MHz

