

# Apacer Technology Inc..

3F, No.83, Kur Wong Rd., Aspire Park, Lung Tan Hsiang,  
Tao Yuan Hsien, Taiwan

## Declaration Letter

Date:2010-Jul-27


**FCC ID: W5EM631**  
**Product Name:Bluetooth Laser Mouse**  
**Model Name:M631**  
**Trade Name:Apacer**

Dear Sir,

Earlier this month we had applied the FCC registration under Apacer Technology Inc. for the product of Bluetooth Laser mouse. However, due to incorrect information by mistake on application form, the Applicant, Manufacturer and Address are wrong and should be corrected as Apacer Technology Inc., and all related address as 3F, No.83, Kur Wong Rd., Aspire Park, Lung Tan Hsiang, Tao Yuan Hsien, Taiwan. The reason to for this correction is to avoid any misunderstanding and commercial disputes in the future.

Here I would like to ask your kindly help to amend this information accordingly at your earlier convenience. Your earlier response is highly appreciated!

Sincerely your



Dairo Wang/Manager  
Apacer Technology Inc.  
3F, No.83, Kur Wong Rd., Aspire Park, Lung Tan Hsiang,  
Tao Yuan Hsien, Taiwan