

Lucy Tsai

From: cindy
Sent: Thursday, March 05, 2009 2:19 AM
To: Lucy Tsai; ss
Subject: Re: Rosewill Inc., FCC ID: W6RRNX-G40, Assessment NO.: AN09T8904, Notice#1-revised
Attachments: Declaration letter.pdf; Exhibit-C-Test_Report rev.pdf; Exhibit-H-External_Photos rev.pdf; Exhibit-J-Conf_Letter rev.pdf; Exhibit-A-Block_Diagram rev.pdf

Dear Lucy,
Please refer the attached document for your requirement, Thanks for your help.

Cindy Huang No. 34, Lin 5, Dingfu Tsuen, Linkou Shiang, Taipei County, 24442, Taiwan
ELECTROMAGNETIC COMPATIBILITY TESTING DEPARTMENT II Electronics Testing Center, Taiwan Tel:
+886-2-26023052 ext. 22 Email:

[_____ URL: _____ ?](#)

-----Original Message-----

From: Lucy Tsai
Sent: Thursday, March 05, 2009 12:52 AM
To: cindy
Subject: FW: Rosewill Inc., FCC ID: W6RRNX-G40, Assessment NO.: AN09T8904, Notice#1

Hi Cindy,

Please address following issues.

Q#1: Inside the PCB, an additional printed antenna is supplied. Please confirm if this printed antenna is workable. If not workable, please provide an attestation letter to confirm it.

ANS: The PCB antenna trace you have mentioned was disconnected to the RF circuit so it has no function. An external antenna was employed only.

Q#2: As indicated in the user manual that channel is selectable which is not acceptable. Please provide an attestation letter to confirm that only 1-11 channels are available in USA. Other channels will be disabled by software.

ANS: See attached attestation letter.

Best Regards,

Lucy Tsai
CCS

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.