10.3. **WORST CASE RADIATED EMISSIONS SETUP**

10.3.1.INTEGRAL ANTENNA





10.3.2. DIPOLE ANTENNA





10.3.3. PCBA ANTENNA






10.3.4.PIFA ANTENNA






10.4. POWERLINE CONDUCTED EMISSIONS MEASUREMENT SETUP



FAX: (510) 661-0888 This report shall not be reproduced except in full, without the written approval of UL CCS.



END OF REPORT