

Request for Class II Permissive Change

FCC ID: W9H32LCD001

Data: Jul 07, 2010

Please be notified that we, the undersigned, Hisense Electric Co., Ltd. declare that the reasons for this Class II permissive change are as below:

1. Update the LCD Panel
2. Update the Power Board

Please refer to below form for details information:

Item	Key Components Deviation				Remark
	LHD32W57US		LCD32W57KCA		
LCD Panel	LTA320AP02	HC315BH-D**	LTA320AP02	LTA320AP05	--
Power Board	HLP-23D01	HLP-30A11	HLP-23D01	HLP-2637WA	--

Thank you.

Sincerely,



Lulu Tang / Supervisor

Hisense Electric Co., Ltd.

Tel: (+86-532)80874377

Fax: (+86-532)80874665

Email: tanglulu@hisense.com