

Request for Class II Permissive Change

FCC ID: W9HLCDE0006

Data: March 31, 2012

Please be notified that we, the undersigned, Hisense Electric Co., Ltd. declare that the reasons for this Class II permissive change are as below:

1. Update LCD Panel
2. Power Board

Please refer to below form for details information:

Item	Key Components Deviation		Remark
	LTDN46K20US	LTDN46K20US(30)	
LCD Panel	HE460FF-B37	HE460FF-B37(0200)	
Power Board	HLL4047WC	HLL-4046WG	
Main chip	--	--	
Tuner	--	--	

Thank you.

Sincerely,



Lulu Tang / Supervisor

Hisense Electric Co., Ltd.

Tel: (+86-532)80874377

Fax: (+86-532)80874665

Email: tanglulu@hisense.com