

Request for Class II Permissive Change

FCC ID: W9HLCDE0007

Data: June 21, 2012

Please be notified that we, the undersigned, Hisense Electric Co., Ltd. declare that the reasons for this Class II permissive change are as below:

1. Update LCD Panel
2. Update Power Board

Please refer to below form for details information:

Item	Key Components Deviation		Remark
	LTDN46K316XWUS3D	LTDN46K316XWUS3D (1)	
LCD Panel	HE460FD-B01	HE460FFD-B31	
Power Board	HLE-4046WE	HLL-4047WF	
Power	115W	100W	
Main chip	MT5325	MT5325	
Tuner	--	--	

Thank you.

Sincerely,



Lulu Tang / Supervisor

Hisense Electric Co., Ltd.

Tel: (+86-532)80874377

Fax: (+86-532)80874665

Email: tanglulu@hisense.com