



Test setup photographs
AC Line Conducted Emissions




Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Models: CFL Sprint MXM Repeater
Test #: 170615A
Test to: 47CFR 15.249(b), RSS-210
File: 58F2DMXMR Short Term Conf TSup Page 1 of 5

S/N's: 348650100197/34866000196
FCC ID: W9Z-58F2DMXMR
IC: 8855A-58F2DMXMR
Date: November 16, 2017


Radiated Emissions



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Models: CFL Sprint MXM Repeater
Test #: 170615A
Test to: 47CFR 15.249(b), RSS-210
File: 58F2DMXMR Short Term Conf TSup


S/N's: 348650100197/34866000196
FCC ID: W9Z-58F2DMXMR
IC: 8855A-58F2DMXMR
Date: November 16, 2017
Page 2 of 5



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Models: CFL Sprint MXM Repeater
Test #: 170615A
Test to: 47CFR 15.249(b), RSS-210
File: 58F2DMXMR Short Term Conf TSup

S/N's: 348650100197/34866000196
FCC ID: W9Z-58F2DMXMR
IC: 8855A-58F2DMXMR
Date: November 16, 2017
Page 3 of 5





Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Models: CFL Sprint MXM Repeater
Test #: 170615A
Test to: 47CFR 15.249(b), RSS-210
File: 58F2DMXMR Short Term Conf TSup

S/N's: 348650100197/34866000196
FCC ID: W9Z-58F2DMXMR
IC: 8855A-58F2DMXMR
Date: November 16, 2017
Page 4 of 5

Antenna Port Conducted Emissions



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
Models: CFL Sprint MXM Repeater
Test #: 170615A
Test to: 47CFR 15.249(b), RSS-210
File: 58F2DMXMR Short Term Conf TSup Page 5 of 5

S/N's: 348650100197/34866000196
FCC ID: W9Z-58F2DMXMR
IC: 8855A-58F2DMXMR

Date: November 16, 2017