

Test setup photographs
AC Line Conducted Emissions




Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
PMN: CFL Sprint MXM Repeater Mk2S
Test: 200911
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMR2S Short Term Conf TSup

S/N's: 331670100442/ 331680100443
FCC ID: W9Z-58F2DMXMR2S
IC: 8855A-58F2DMXMR2S
Date: January 15, 2021
Page 1 of 5


Radiated Emissions



Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
PMN: CFL Sprint MXM Repeater Mk2S
Test: 200911
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMR2S Short Term Conf TSup

S/N's: 331670100442/ 331680100443
FCC ID: W9Z-58F2DMXMR2S
IC: 8855A-58F2DMXMR2S
Date: January 15, 2021
Page 2 of 5



Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
PMN: CFL Sprint MXM Repeater Mk2S
Test: 200911
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMR2S Short Term Conf TSup

S/N's: 331670100442/ 331680100443
FCC ID: W9Z-58F2DMXMR2S
IC: 8855A-58F2DMXMR2S
Date: January 15, 2021
Page 3 of 5



Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
PMN: CFL Sprint MXM Repeater Mk2S
Test: 200911
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMR2S Short Term Conf TSup

S/N's: 331670100442/ 331680100443
FCC ID: W9Z-58F2DMXMR2S
IC: 8855A-58F2DMXMR2S
Date: January 15, 2021
Page 4 of 5



Rogers Labs, Inc.
4405 W. 259th Terr
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

SAF Tehnika AS
PMN: CFL Sprint MXM Repeater Mk2S
Test: 200911
Test to: 47CFR, 15.407, RSS-247
File: 58F2DMXMR2S Short Term Conf TSup

S/N's: 331670100442/ 331680100443
FCC ID: W9Z-58F2DMXMR2S
IC: 8855A-58F2DMXMR2S
Date: January 15, 2021
Page 5 of 5