


11035 Block Diagram 2008.5.26



OPTION: If there is only one connection for USB, just connect it to USB/VBUS.
OPTION: If PWM can be used to control LED brightness for Self-Timer LED, remove this Tr.

- Boot Set (FA15~FA19)
USB Boot (1010)
Nand Flash (10100)