

December 31, 2008.

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia, MD 21046

Re: FCC ID: WDC-IQ2008

Model# : IQ2008L

TO Whom It May Concern:

This will serve as a Class II Permissive Change request for the above mentioned FCC Identifier.

The manufacturer has had to change to a different device in the controller.

The original radio was approved using the CPU AR5010. The vender is having supply problems and wishes to use the Micro-controller TMP86FS23UG plus the Docorder S7041B as a substitute. There are some other component change in addition.

Further to the above changes for Model# : IQ2008, this low-lost Model# : IQ2008 deletes voice function(speaber writ and some components)

We have performed radiated emissions testing and there in no degradation from the original test data. The data in the test report shows that it still continues to meet the FCC requirements for this class or equipment.

Should you have any questions or require any further information, please advise

Sincerely,

K.T Kang/President