

August 30<sup>th</sup>, 2019

CETCB 114 Olinda Drive

Brea, CA 92823 Attn: CETCB Ref: FCC Class II Permissive change for FCC ID: WDQ-RPTR1345 (Original Grant date: 11/23/2016)

Applicant: Nortek Security & Control LLC

Dear Examiner, This is to request a Class II permissive change for FCC ID: WDQ-RPTR1345, originally granted on 11/23/2016. The major changes filed under this application is:

Change #1 New firmware which results in duty cycle increased from 10.11% to 12.66% (given 100ms window) due to larger packet payload. The end user cannot modify the duty cycle.

Change #2 New firmware to lower the gain setting to a level of "10".

No other changes have been made to this product.

If you have any questions regarding this application, please feel free to contact me. Sincerely yours,

Torey Oliver Regulatory Compliance Engineer

rimer

