



2gig technologies

Model #: 2GIG-SMKT2-345

FCC ID: WDQ-SMKT2345

IC: 7794A-SMKT2345

Made in China

twice a year. Test weekly by depressing test  
button. Alarm sound: temporal. Son d'alarme:  
temporel. Trouble sound: chirp. Son de  
defectuosite: carillon. For details see install in st  
#1039047. Pour details regards aux instructions  
d'in stallations #1039047.

This device complies with part 15 of the FCC rules, is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.


08261S

WARNING: Cannot be mounted & will not operate without batteries



# WARNING

Use only batteries specified in marking. Use of a different battery will have a detrimental effect on detector operation. When replacing batteries remove all batteries; wait 30 seconds after removal before inserting new batteries. For proper operation use only 3.



Model #: 2GIG-SMKT2-345  
FCC ID: WDQ-SMKT2345  
IC: 7794A-SMKT2345  
Made in China

S/N#: 000-0269

Model: 562NST  
Self diagnostic photoelectric smoke detector.  
Sensitivity 0.88 to 3.63 %/ft. Do not use where ambient temp exceeds 100°F(37.8°C).  
Power up time 15 sec. Operating voltage: 3.0 VDC. Heat sensor rating: Fixed 135°F(57°C). Rate of rise > 15°F/min(8.3°C/min). Requires servicing when LED does not flash. Vacuum button. Alarm sound: temporal. Son d'alarme: temporel. Trouble sound: chirp. Son de defectuosite: carillon. For details see install in #1039047. Pour details regards aux instructions d'installations #1039047