

APPENDIX A Tel: +886 2 26099301 Fax: +886 2 26099303

APPENDIX A

TEST PHOTOGRAPHS

(Model: GWS-QX.)

File Number: C1M1601202 This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.

Report Number: EM-F160088




New Taipei City244, Taiwan

APPENDIX A-Page 1 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

A.1 Conducted Emission Measurement



FRONT VIEW



SIDE VIEW

File Number: C1M1601202

Report Number: EM-F160088


This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX A-Page 2 of 4

Tel: +886 2 26099301 *Fax:* +886 2 26099303

A.2 Radiated Measurement at Anechoic Chamber Frequency Below 1GHz



Frequency Above 1GHz



Report Number: EM-F160088

This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



AUDIX Technology Corp. No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX A-Page 3 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303


Zoom View





No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX A-Page 4 of 4 Tel: +886 2 26099301 Fax: +886 2 26099303

A.3 RF Conducted Measurement



File Number: C1M1601202

Report Number: EM-F160088

This test report may be reproduced in full only. The document may only be updated by AUDIX Technology Corp. personnel. Any changes will be noted in the Document History section of the report.