



Date: 2 NOV 2023 22:27:18

11AC20SISO\_Ant2\_5700




Date: 2 NOV 2023 22:29:33

11AC20SISO\_Ant2\_5720




Date: 2 NOV 2023 22:31:25

11AC20SISO\_Ant2\_5745




Date: 2 NOV 2023 22:34:02

11AC20SISO\_Ant2\_5785




Date: 2 NOV 2023 22:36:15

11AC20SISO\_Ant2\_5825




Date: 2 NOV 2023 22:38:37

11AC40SISO\_Ant2\_5190




Date: 3.NOV.2023 09:34:44

11AC40SISO\_Ant2\_5230




Date: 3.NOV.2023 09:38:23

11AC40SISO\_Ant2\_5270




Date: 3.NOV.2023 09:40:21

11AC40SISO\_Ant2\_5310




Date: 3.NOV.2023 09:43:02

11AC40SISO\_Ant2\_5510




Date: 3.NOV.2023 09:48:01

11AC40SISO\_Ant2\_5550




Date: 3.NOV.2023 09:50:35

11AC40SISO\_Ant2\_5670




Date: 3 NOV 2023 09:54:51

11AC40SISO\_Ant2\_5710




Date: 3 NOV 2023 09:57:02

11AC40SISO\_Ant2\_5755




Date: 3 NOV 2023 09:59:40

11AC40SISO\_Ant2\_5795




Date: 3.NOV.2023 10:01:51

11AC80SISO\_Ant2\_5210




Date: 3.NOV.2023 10:47:49

11AC80SISO\_Ant2\_5290




Date: 3.NOV.2023 10:50:48

11AC80SISO\_Ant2\_5530




Date: 3.NOV.2023 10:52:47

11AC80SISO\_Ant2\_5610




Date: 3.NOV.2023 10:55:44

11AC80SISO\_Ant2\_5690



Date: 3.NOV.2023 10:57:50





11AC80SISO\_Ant2\_5775




Date: 3.NOV.2023 11:00:41




99% Bandwidth





Date: 2 NOV 2023 14:40:58

11A\_Ant1\_5280



Date: 2 NOV 2023 14:42:44

11A\_Ant1\_5320




Date: 2 NOV 2023 14:44:26


11A\_Ant1\_5500




11A\_Ant1\_5580




11A\_Ant1\_5700




11A\_Ant1\_5720



11A\_Ant1\_5745



11A\_Ant1\_5785




11A\_Ant1\_5825




Date: 2 NOV 2023 15:03:31

11N20SISO\_Ant1\_5180




Date: 2 NOV 2023 15:07:34

11N20SISO\_Ant1\_5200




Date: 2 NOV 2023 15:12:42

11N20SISO\_Ant1\_5240




Date: 2 NOV 2023 15:17:25

11N20SISO\_Ant1\_5260



Date: 2 NOV 2023 15:22:23

11N20SISO\_Ant1\_5280




Date: 2 NOV 2023 15:24:29

11N20SISO\_Ant1\_5320




Date: 2 NOV 2023 15:27:44

11N20SISO\_Ant1\_5500




Date: 2 NOV 2023 15:30:57

11N20SISO\_Ant1\_5580




Date: 2 NOV 2023 15:40:28

11N20SISO\_Ant1\_5700




Date: 2 NOV 2023 15:43:38

11N20SISO\_Ant1\_5720



Date: 2 NOV 2023 15:46:27


11N20SISO\_Ant1\_5745



Date: 2 NOV 2023 15:49:28


11N20SISO\_Ant1\_5785






Date: 2 NOV 2023 15:51:05

11N20SISO\_Ant1\_5825



Date: 2 NOV 2023 15:54:31

11N40SISO\_Ant1\_5190




Date: 2 NOV 2023 15:56:15

11N40SISO\_Ant1\_5230




Date: 2 NOV 2023 15:58:22

11N40SISO\_Ant1\_5270



Date: 2 NOV 2023 16:00:44

11N40SISO\_Ant1\_5310



Date: 2 NOV 2023 16:02:16


11N40SISO\_Ant1\_5510




11N40SISO\_Ant1\_5550



11N40SISO\_Ant1\_5670




11N40SISO\_Ant1\_5710




Date: 2 NOV 2023 16:11:22

11N40SISO\_Ant1\_5755




Date: 2 NOV 2023 16:13:17

11N40SISO\_Ant1\_5795




Date: 2 NOV 2023 16:15:13

11AC20SISO\_Ant1\_5180




Date: 2 NOV 2023 16:18:07

11AC20SISO\_Ant1\_5200




Date: 2 NOV 2023 16:21:34

11AC20SISO\_Ant1\_5240




Date: 2 NOV 2023 16:24:08


11AC20SISO\_Ant1\_5260



11AC20SISO\_Ant1\_5280




11AC20SISO\_Ant1\_5320




11AC20SISO\_Ant1\_5500




11AC20SISO\_Ant1\_5580



11AC20SISO\_Ant1\_5700




11AC20SISO\_Ant1\_5720




Date: 2 NOV 2023 17:02:16

11AC20SISO\_Ant1\_5745



Date: 2 NOV 2023 17:05:00


11AC20SISO\_Ant1\_5785



Date: 2 NOV 2023 17:08:22


11AC20SISO\_Ant1\_5825





Date: 2 NOV 2023 17:13:28

11AC40SISO\_Ant1\_5190



Date: 2 NOV 2023 17:15:38

11AC40SISO\_Ant1\_5230



Date: 2 NOV 2023 17:20:14

11AC40SISO\_Ant1\_5270



Date: 2 NOV 2023 17:22:27

11AC40SISO\_Ant1\_5310




Date: 2 NOV 2023 17:24:32

11AC40SISO\_Ant1\_5510




Date: 2 NOV 2023 17:26:30

11AC40SISO\_Ant1\_5550




Date: 2 NOV 2023 17:28:56

11AC40SISO\_Ant1\_5670



Date: 2 NOV 2023 17:30:48

11AC40SISO\_Ant1\_5710




Date: 2 NOV 2023 17:33:02


11AC40SISO\_Ant1\_5755




11AC40SISO\_Ant1\_5795




11AC80SISO\_Ant1\_5210




11AC80SISO\_Ant1\_5290




11AC80SISO\_Ant1\_5530



11AC80SISO\_Ant1\_5610




11AC80SISO\_Ant1\_5690




Date: 2 NOV 2023 17:52:31

11AC80SISO\_Ant1\_5775




Date: 2 NOV 2023 17:55:28

11A\_Ant2\_5180




Date: 2 NOV 2023 18:05:11

11A\_Ant2\_5200




Date: 2 NOV 2023 18:07:58

11A\_Ant2\_5240



Date: 2 NOV 2023 18:09:42

11A\_Ant2\_5260




Date: 2 NOV 2023 18:11:50

11A\_Ant2\_5280




Date: 2 NOV 2023 18:15:12

11A\_Ant2\_5320



Date: 2 NOV 2023 20:00:06


11A\_Ant2\_5500



Date: 2 NOV 2023 18:20:41


11A\_Ant2\_5580






Date: 2 NOV 2023 18:22:48

11A\_Ant2\_5700




Date: 2 NOV 2023 18:25:21

11A\_Ant2\_5720




Date: 2 NOV 2023 20:05:12

11A\_Ant2\_5745




Date: 2 NOV 2023 20:08:19

### 11A\_Ant2\_5785




Date: 2 NOV 2023 20:10:47

### 11A\_Ant2\_5825




Date: 2 NOV 2023 20:12:56

### 11N20SISO\_Ant2\_5180




Date: 2 NOV 2023 20:15:28

### 11N20SISO\_Ant2\_5200




Date: 2 NOV 2023 20:18:19

### 11N20SISO\_Ant2\_5240




Date: 2 NOV 2023 20:20:24

### 11N20SISO\_Ant2\_5260




11N20SISO\_Ant2\_5280



11N20SISO\_Ant2\_5320




11N20SISO\_Ant2\_5500




Date: 2 NOV 2023 21:04:34

11N20SISO\_Ant2\_5580




Date: 2 NOV 2023 21:06:40

11N20SISO\_Ant2\_5700




Date: 2 NOV 2023 21:08:34

11N20SISO\_Ant2\_5720




Date: 2.NOV.2023 21:10:50

11N20SISO\_Ant2\_5745




Date: 2.NOV.2023 21:14:07

11N20SISO\_Ant2\_5785




Date: 2.NOV.2023 21:17:01

11N20SISO\_Ant2\_5825



Date: 2 NOV 2023 21:20:24

11N40SISO\_Ant2\_5190



Date: 2 NOV 2023 21:22:55

11N40SISO\_Ant2\_5230




Date: 2 NOV 2023 21:25:08

11N40SISO\_Ant2\_5270




Date: 2 NOV 2023 21:27:52

### 11N40SISO\_Ant2\_5310



Date: 2 NOV 2023 21:30:16


### 11N40SISO\_Ant2\_5510



Date: 2 NOV 2023 21:32:20


### 11N40SISO\_Ant2\_5550






Date: 2 NOV 2023 21:37:02

11N40SISO\_Ant2\_5670




Date: 2 NOV 2023 22:01:11

11N40SISO\_Ant2\_5710




Date: 2 NOV 2023 22:03:25

11N40SISO\_Ant2\_5755




Date: 2 NOV 2023 22:06:22

11N40SISO\_Ant2\_5795




Date: 2 NOV 2023 22:09:03

11AC20SISO\_Ant2\_5180




Date: 2 NOV 2023 22:11:08

11AC20SISO\_Ant2\_5200




Date: 2 NOV 2023 22:13:27

11AC20SISO\_Ant2\_5240




Date: 2 NOV 2023 22:18:07

11AC20SISO\_Ant2\_5260




Date: 2 NOV 2023 22:17:46

11AC20SISO\_Ant2\_5280




Date: 2 NOV 2023 22:20:19

11AC20SISO\_Ant2\_5320




Date: 2 NOV 2023 22:22:30

11AC20SISO\_Ant2\_5500




Date: 2 NOV 2023 22:24:49


11AC20SISO\_Ant2\_5580




11AC20SISO\_Ant2\_5700




11AC20SISO\_Ant2\_5720




11AC20SISO\_Ant2\_5745




11AC20SISO\_Ant2\_5785



11AC20SISO\_Ant2\_5825



11AC40SISO\_Ant2\_5190



Date: 3 NOV 2023 09:34:56

11AC40SISO\_Ant2\_5230




Date: 3 NOV 2023 09:38:34

11AC40SISO\_Ant2\_5270




Date: 3 NOV 2023 09:40:32

11AC40SISO\_Ant2\_5310



Date: 3.NOV.2023 09:43:13

11AC40SISO\_Ant2\_5510



Date: 3.NOV.2023 09:48:13

11AC40SISO\_Ant2\_5550




Date: 3.NOV.2023 09:50:46

11AC40SISO\_Ant2\_5670







11AC40SISO\_Ant2\_5710



11AC40SISO\_Ant2\_5755




11AC40SISO\_Ant2\_5795




Date: 3 NOV 2023 10:02:03

11AC80SISO\_Ant2\_5210




Date: 3 NOV 2023 10:48:01

11AC80SISO\_Ant2\_5290




Date: 3 NOV 2023 10:50:59

11AC80SISO\_Ant2\_5530




Date: 3 NOV 2023 10:52:59

11AC80SISO\_Ant2\_5610



Date: 3 NOV 2023 10:55:55

11AC80SISO\_Ant2\_5690



Date: 3 NOV 2023 10:58:03

11AC80SISO\_Ant2\_5775

