

04 August 2011

attn: Reviewing Engineer Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

## To Whom It May Concern:

- 1.3 The, Wireless Magnetic Contact Sensor FCC ID: WP3MCT320SMA and label is so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3)

  "This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:
- (1) This device may not cause harmful interference and
  - (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Thank you,

Arick Elshtein



Tel: 972 3 6456789 Fax: 972 3 6456788