


## Annex C: Internal photographs



152541\_1i.JPG: RFU650-10101, internal view, housing opened


Annex C: Internal photographs



152541\_1d.JPG: RFU650-10101, internal view




**Annex C: Internal photographs**



152541\_1n.JPG: RFU650-10101, internal view, antenna cover removed (supplied by the applicant)


**Annex C: Internal photographs**



152541\_1o.JPG: RFU650-10101, internal view, antenna PCBs removed (supplied by the applicant)




### Annex C: Internal photographs



152541\_1e.JPG: RFU650-10101, PCB 1, top view


**Annex C: Internal photographs**



152541\_1f.JPG: RFU650-10101, PCB 1, bottom view




## Annex C: Internal photographs



152541\_1g.JPG: RFU650-10101, PCB 2, top view


### Annex C: Internal photographs



152541\_1h.JPG: RFU650-10101, PCB 2, bottom view



**Annex C: Internal photographs**



152541\_1p.JPG: RFU650-10101, antenna PCBs, top and bottom view (supplied by the applicant)