

Appendix B - Photographs


DC EQUIPMENT EXTERNAL VIEW




AC EQUIPMENT EXTERNAL VIEW



GENERAL SET-UP FOR RADIATED MEASUREMENTS



TEST SET-UP FOR RADIATED MEASUREMENTS BELOW 1 GHz



TEST SET-UP FOR RADIATED MEASUREMENTS ABOVE 1GHz



TEST SET-UP FOR CONDUCTED MEASUREMENTS

