

Description of Permissive Change

The report is prepared for FCC class II permissive change. The difference compared with original report is listing as below:

- 1. Converting the DTS filing from 15.247 to 15.407 under new rule
- 2. Updating U-NII filing to under new rule.
- 3. Changing PCB RF layout (only effect RX only) and thermal pad.
- 4. Adding console pin.
- 5. Changing appearance of EUT.
- 6. Changing Capacitance and Resistor (for ISN LAN port).

Andrea Hsia

Senior Specialist

Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch

Tel: 886-3-318 3232 ext. 1628

Fax: 886-3-3270892

Email: andrea.hsia@tw.bureauveritas.com

Data: 2016-01-28

Reference no.: RF151124C19