

Brightstar Corporation

9725 NW 117th Ave.,Miami,Florida,United States,33178

Tel: 1 305.921-1470 ; Fax: 1 305.863-3367

Federal Communications Commission

Authorization and Evaluation Division

1435 Oakland Mills Road

Columbia, MD 21046

SUBJECT: Class II Permissive Change for FCC ID: WVBA921

The product, Mobile phone, has been granted by FCC dated July 05, 2012, FCC ID: WVBA921.

Now we, Brightstar Corporation, would like to modify the authorized equipment for below changes:

1. Bluetooth part: resistor C501 is change from 0 ohms to 1 ohm
2. RF part:

Part Reference	Previous model of Avvio 921	Current model of Avvio 921
SF600	No	S)FILTER,SAW,EGSM/DCS RX,SFW942PY002,WISOL
C632	No	22pF
C640	No	6pF
C628 C629	No	2pF
L609 L611	No	18nH 4.7nH
C630 C633	No	2.7pF
C623 C627	22pF 10nH	1.0nH 5.6nH

3. SIM part: Current model of Avvio 921 have two SIM slot, while previous have only one SIM slot.

Except for the change above, no other modification is performed. Also, the change does not have any impact on the approved radio parameter such as power, frequency range, modulation etc.

We would like to certify the additional of certified FCC ID: WVBA921 as a Class II Permissive Change in this device.

Sincerely,



Welton G. G. G.