

## LETTER OF ATTESTATION

Ladies and or Gentlemen:



The Control Key Pad Console was wired to the Power Unit for testing and it was determined that the following measures were needed to have the units operate within the parameters set down by the FCC & Industry Canada:

- 1. A ferrite (Fair-Rite 0431167281) was placed inside the transceiver unit at the Power Supply pcbrd (black & white wires, two passes) to lower broadband noise @ appx 83.5MHz.
- 2. Added Fair-Rite #0431164281 to power supply board output wires (one pass) inside unit.

The manufacturer attests to the fact that these ferrites will be added to the power supply at the factory.

Dated th	nis 97/4	day o	f	Mr Clt	, 20 <u>1</u> 3	
Ву	Shal Cu	t		Gre	AHAM S. DUTHI	2
	Signature				Printed	
Title	TV CHALLCON	(FACE	T	Talanhona	(651) 264-4805	