



Internal view 1, housing opened

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 1 of 17





Internal view, front cover and main part

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 2 of 17





Internal view 3, front cover, shielding removed

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 3 of 17





Internal view 4, front cover, PCBs removed

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 4 of 17





Main part, PCB 4 removed

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 5 of 17





Main part, shielding removed

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 6 of 17





Main part, main PCB removed

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 7 of 17






PCB 1, top view

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 8 of 17





PCB 1, bottom view

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 9 of 17






PCB 2 and 3, top view

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 10 of 17





PCB 2 and 3, bottom view

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 11 of 17






PCB 4, top view

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 12 of 17





PCB 4, bottom view

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 13 of 17





PCB 5, top view

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 14 of 17





PCB 5, top view, shieldings removed

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 15 of 17





PCB 5, bottom view

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 16 of 17





PCB 5, bottom view, shieldings removed

 Examiner:
 Thomas KÜHN
 Revision:
 00

 Date of issue:
 22.04.2022
 Order Number:
 22-110214
 page 17 of 17