



## Transceiver

risk of fire or electrical shock, do not expose this equipment to rain or moisture. Do not remove (metal) cover, no user serviceable parts inside. Refer servicing to qualified personnel. Circuit Fuses inside only, contact Service representative for replacement or repair.

## FCC ID: X2PCRLU-201

This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful Interference, and
- (2) This device must accept any interference received, Including interference that may cause undesired operation.