

Redpine Signals, Inc. 9th Floor ,Maximus Towers '2B' Raheja Mindsapce IT Park MadhapurHyderabad – 500081, India

Ph: +91-40-39351000

Date: 29August 2013

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Re:

Request to Change in Identification:

Dear Examiner,

This change of identification request applies for FCC ID: XF6-RS9110N1124 as established in 47CFR 2.933(b) for a currently approved device. This application by Redpine Signals Inc will establish a new FCC ID: XF6-RS9110N1122 for purpose of marketing. The original grant to Redpine Signals Inc will remain in effect per 2.933(b).

1. The original identification is FCC ID: XF6-RS9110N1124

2. The original grant date is 07/30/2013

- 3. The equipment is electrically identical, only application and FCC ID are different
- 4. The original test results are applicable and representative of this changed device

5. Exterior photographs are include in this application

The following files are electronically submitted as attachments:

External Photos of New Application
FCC ID Label Format and location of New Application

Sincerely,

Name: Chandra Sekhar Abburi

Title: VP-Systems

On behalf of Redpine Signals Inc

Phone: +91 40 39351008