



Please refer to following plots:

### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 18.NOV.2022 17:29:38

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 18.NOV.2022 17:29:53

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 18.NOV.2022 17:30:15

Band 7\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 18.NOV.2022 17:30:33

Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 18.NOV.2022 17:30:52

Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 18.NOV.2022 17:31:13

Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 18.NOV.2022 18:14:53

Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 18.NOV.2022 18:15:12

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 18.NOV.2022 18:15:31

Band 7\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 18.NOV.2022 18:15:50

Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 18.NOV.2022 18:16:16

Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 18.NOV.2022 18:16:38

Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 18.NOV.2022 18:17:36

Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 18.NOV.2022 18:18:00

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0



Date: 18.NOV.2022 18:18:22


Band 7\_15 MHz\_Middle\_16QAM\_RB75#0



Date: 18.NOV.2022 18:18:43




Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 18.NOV.2022 18:19:05

Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 18.NOV.2022 18:19:29

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 18.NOV.2022 18:20:26

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 18.NOV.2022 18:20:48

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 18.NOV.2022 18:21:07

Band 7\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 18.NOV.2022 18:21:32

Band 7\_20 MHz\_High\_QPSK\_RB100#0




Date: 18.NOV.2022 18:21:51

Band 7\_20 MHz\_High\_16QAM\_RB100#0




Date: 18.NOV.2022 18:24:28

### Band 14\_5 MHz\_Low\_QPSK\_RB25#0




Date: 12.NOV.2022 18:24:50

### Band 14\_5 MHz\_Low\_16QAM\_RB25#0




Date: 12.NOV.2022 18:25:11

Band 14\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 12.NOV.2022 18:25:28

Band 14\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 12.NOV.2022 18:25:51

Band 14\_5 MHz\_High\_QPSK\_RB25#0




Date: 12.NOV.2022 18:26:12

Band 14\_5 MHz\_High\_16QAM\_RB25#0




Date: 12.NOV.2022 18:26:32

Band 14\_10 MHz\_Middle\_QPSK\_RB50#0



Date: 12.NOV.2022 18:28:15


Band 14\_10 MHz\_Middle\_16QAM\_RB50#0



Date: 12.NOV.2022 18:28:35




Band 30\_5 MHz\_Low\_QPSK\_RB25#0




Date: 12.NOV.2022 18:29:03

Band 30\_5 MHz\_Low\_16QAM\_RB25#0




Date: 12.NOV.2022 18:29:19

Band 30\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 12.NOV.2022 18:29:40

Band 30\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 12.NOV.2022 18:30:00

### Band 30\_5 MHz\_High\_QPSK\_RB25#0




Date: 12.NOV.2022 18:30:18

### Band 30\_5 MHz\_High\_16QAM\_RB25#0




Date: 12.NOV.2022 18:30:38

### Band 30\_10 MHz\_Middle\_QPSK\_RB50#0



Date: 13.DEC.2022 15:10:03

### Band 30\_10 MHz\_Middle\_16QAM\_RB50#0



Date: 13.DEC.2022 15:13:37