



Please refer to following plots:

Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:25:56

Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:26:06

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:26:20

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:26:31

Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:26:45

Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:26:55

Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:28:05

Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:28:16

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:28:30

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:28:41

Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:28:56

Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:29:06

Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:29:57

Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:30:07

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)



Date: 18.NOV.2022 18:30:25


Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)



Date: 18.NOV.2022 18:30:35




Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:30:55

Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:31:06

Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:31:57

Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:32:07

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:32:25

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:32:35

Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 18.NOV.2022 18:32:56

Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 18.NOV.2022 18:33:07

### Band 14\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.NOV.2022 19:25:32

### Band 14\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.NOV.2022 19:25:43

Band 14\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.NOV.2022 19:25:59

Band 14\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.NOV.2022 19:26:09

Band 14\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 12.NOV.2022 19:26:22

Band 14\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 12.NOV.2022 19:26:32

### Band 14\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)



Date: 12.NOV.2022 19:27:29


### Band 14\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)



Date: 12.NOV.2022 19:27:39




### Band 30\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-2.288GHz)




Date: 13.DEC.2022 16:23:38

### Band 30\_5 MHz\_Low\_QPSK\_RB25#0\_2(2.365GHz-15GHz)




Date: 13.DEC.2022 16:24:16

### Band 30\_5 MHz\_Low\_QPSK\_RB25#0\_3(15GHz-25GHz)




Date: 13.DEC.2022 16:24:54

### Band 30\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-2.288GHz)




Date: 13.DEC.2022 16:26:38

### Band 30\_5 MHz\_Middle\_QPSK\_RB25#0\_2(2.365GHz-15GHz)




Date: 13.DEC.2022 16:27:16

### Band 30\_5 MHz\_Middle\_QPSK\_RB25#0\_3(15GHz-25GHz)




Date: 13.DEC.2022 16:27:54

### Band 30\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-2.288GHz)




Date: 13.DEC.2022 16:31:04

### Band 30\_5 MHz\_High\_QPSK\_RB25#0\_2(2.365GHz-15GHz)




Date: 13.DEC.2022 16:31:42

### Band 30\_5 MHz\_High\_QPSK\_RB25#0\_3(15GHz-25GHz)




Date: 13.DEC.2022 16:32:20

### Band 30\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-2.288GHz)




Date: 13.DEC.2022 16:33:10

### Band 30\_10 MHz\_Middle\_QPSK\_RB50#0\_2(2.365GHz-15GHz)



Date: 15.DEC.2022 09:19:41

### Band 30\_10 MHz\_Middle\_QPSK\_RB50#0\_3(15GHz-25GHz)



Date: 13.DEC.2022 16:34:25