

Franklin Technology Inc.  
Address: 906 JEI Platz, 186, Gasan digital 1-ro, Gumcheon-Gu Seoul, South Korea  
Tel: 82-70-8228-6445  
Email: win2337@franklintech.co.kr

---

Date: 2022-11-25

## Declaration Letter

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road  
Columbia, MD 21046

Dear Sir/Madam,

We, Franklin Technology Inc., hereby declare that we have a product named as Mobile Hotspot,(model: RG2102, FCC ID: XHG-RG2102) tested by ATC(Shenzhen), a complete module (Model :M2600,FCC ID: XHG-M2500) is installed inside the product, we did not make any modification on the module hardware, but only shielded part of the frequency band through software, and other are the same, so all RF parameters refer to module data.

For marketing purpose, The Mobile Hotspot RG2102 and the module M2600 only supports Bands as follow

	M2600 (FCC ID: XHG-M2500)	RG2102(XHG-RG2102)
Supported Bands	3G UMTS: B2/B4/B5 LTE :B2/B4/B5/B7/B12/B14/B25/B26/ B29/B30/B41/B48/B66/B71 FR1 : n2/n5/n25/n41/n48/n66/n71/n77 DC_2A_n5A/5A_n66A/5A_n2A/2A_n66A /66A_n2A	3G UMTS: B2/B5 LTE : B2/B4/B5/B7/B12/B14/B30/B48/B66 FR1 : n2/n5/n66/n77/ DC_2A_n5A/DC_5A_n66A/DC_5A_n2A/DC_2A_n 66A/DC_66A_n2A

And the Carrier Aggregation (CA) function was disabled to use by manufacture in the software, the end user has no capability to activate it

For Wi-Fi 802.11 ax mode, the partial RU mode was disabled to use by manufacture in the software, the end user have no capability to activate it.

We confirm that all information above is true, and we'll be responsible for all the consequences.  
Please contact me if you have any question.

Signature:



James Lee

R&D HW team Leader