



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0




Date: 7.OCT.2022 20:07:38

Band 2_1.4 MHz_Low_16QAM_RB6#0




Date: 7.OCT.2022 20:07:45

Band 2_1.4 MHz_High_QPSK_RB6#0




Date: 7.OCT.2022 20:07:52

Band 2_1.4 MHz_High_16QAM_RB6#0




Date: 7.OCT.2022 20:07:59

Band 2_3 MHz_Low_QPSK_RB15#0




Date: 7.OCT.2022 20:08:36

Band 2_3 MHz_Low_16QAM_RB15#0




Date: 7.OCT.2022 20:08:42

Band 2_3 MHz_High_QPSK_RB15#0




Date: 7.OCT.2022 20:08:50

Band 2_3 MHz_High_16QAM_RB15#0




Date: 7.OCT.2022 20:08:57

Band 2_5 MHz_Low_QPSK_RB25#0




Date: 7.OCT.2022 20:09:35

Band 2_5 MHz_Low_16QAM_RB25#0




Date: 7.OCT.2022 20:09:42

Band 2_5 MHz_High_QPSK_RB25#0




Date: 7.OCT.2022 20:09:50

Band 2_5 MHz_High_16QAM_RB25#0




Date: 7.OCT.2022 20:09:57

Band 2_10 MHz_Low_QPSK_RB50#0




Date: 7.OCT.2022 20:10:37

Band 2_10 MHz_Low_16QAM_RB50#0




Date: 7.OCT.2022 20:10:45

Band 2_10 MHz_High_QPSK_RB50#0




Date: 7.OCT.2022 20:10:53

Band 2_10 MHz_High_16QAM_RB50#0




Date: 7.OCT.2022 20:11:01

Band 2_15 MHz_Low_QPSK_RB75#0




Date: 7.OCT.2022 20:11:40

Band 2_15 MHz_Low_16QAM_RB75#0




Date: 7.OCT.2022 20:11:47

Band 2_15 MHz_High_QPSK_RB75#0




Date: 7.OCT.2022 20:11:55

Band 2_15 MHz_High_16QAM_RB75#0




Date: 7.OCT.2022 20:12:02

Band 2_20 MHz_Low_QPSK_RB100#0




Date: 7.OCT.2022 20:12:41

Band 2_20 MHz_Low_16QAM_RB100#0




Date: 7.OCT.2022 20:12:48

Band 2_20 MHz_High_QPSK_RB100#0




Date: 7.OCT.2022 20:12:56

Band 2_20 MHz_High_16QAM_RB100#0




Date: 7.OCT.2022 20:13:03

Band 4_1.4 MHz_Low_QPSK_RB6#0




Date: 7.OCT.2022 20:15:24

Band 4_1.4 MHz_Low_16QAM_RB6#0




Date: 7.OCT.2022 20:15:31

Band 4_1.4 MHz_High_QPSK_RB6#0




Date: 7.OCT.2022 20:15:38

Band 4_1.4 MHz_High_16QAM_RB6#0




Date: 7.OCT.2022 20:15:44

Band 4_3 MHz_Low_QPSK_RB15#0




Date: 7.OCT.2022 20:17:21

Band 4_3 MHz_Low_16QAM_RB15#0




Date: 7.OCT.2022 20:17:28

Band 4_3 MHz_High_QPSK_RB15#0




Date: 7.OCT.2022 20:17:34

Band 4_3 MHz_High_16QAM_RB15#0




Date: 7.OCT.2022 20:17:40

Band 4_5 MHz_Low_QPSK_RB25#0




Date: 7.OCT.2022 20:18:18

Band 4_5 MHz_Low_16QAM_RB25#0




Date: 7.OCT.2022 20:18:25

Band 4_5 MHz_High_QPSK_RB25#0




Date: 7.OCT.2022 20:18:33

Band 4_5 MHz_High_16QAM_RB25#0




Date: 7.OCT.2022 20:18:40

Band 4_10 MHz_Low_QPSK_RB50#0




Date: 7.OCT.2022 20:20:39

Band 4_10 MHz_Low_16QAM_RB50#0




Date: 7.OCT.2022 20:20:47

Band 4_10 MHz_High_QPSK_RB50#0




Date: 7.OCT.2022 20:20:55

Band 4_10 MHz_High_16QAM_RB50#0




Date: 7.OCT.2022 20:21:03

Band 4_15 MHz_Low_QPSK_RB75#0




Date: 7.OCT.2022 20:23:49

Band 4_15 MHz_Low_16QAM_RB75#0




Date: 7.OCT.2022 20:23:56

Band 4_15 MHz_High_QPSK_RB75#0




Date: 7.OCT.2022 20:24:04

Band 4_15 MHz_High_16QAM_RB75#0




Date: 7.OCT.2022 20:24:11

Band 4_20 MHz_Low_QPSK_RB100#0




Date: 7.OCT.2022 20:25:09

Band 4_20 MHz_Low_16QAM_RB100#0




Date: 7.OCT.2022 20:25:16

Band 4_20 MHz_High_QPSK_RB100#0




Date: 7.OCT.2022 20:25:24

Band 4_20 MHz_High_16QAM_RB100#0




Date: 7.OCT.2022 20:25:31

Band 5_1.4 MHz_Low_QPSK_RB6#0




Date: 7.OCT.2022 20:26:13

Band 5_1.4 MHz_Low_16QAM_RB6#0




Date: 7.OCT.2022 20:26:19

Band 5_1.4 MHz_High_QPSK_RB6#0




Date: 7.OCT.2022 20:26:26

Band 5_1.4 MHz_High_16QAM_RB6#0




Date: 7.OCT.2022 20:26:32

Band 5_3 MHz_Low_QPSK_RB15#0




Date: 7.OCT.2022 20:27:09

Band 5_3 MHz_Low_16QAM_RB15#0




Date: 7.OCT.2022 20:27:16

Band 5_3 MHz_High_QPSK_RB15#0




Date: 7.OCT.2022 20:27:23

Band 5_3 MHz_High_16QAM_RB15#0




Date: 7.OCT.2022 20:27:29

Band 5_5 MHz_Low_QPSK_RB25#0




Date: 7.OCT.2022 20:28:08

Band 5_5 MHz_Low_16QAM_RB25#0




Date: 7.OCT.2022 20:28:14

Band 5_5 MHz_High_QPSK_RB25#0




Date: 7.OCT.2022 20:28:22

Band 5_5 MHz_High_16QAM_RB25#0




Date: 7.OCT.2022 20:28:29

Band 5_10 MHz_Low_QPSK_RB50#0




Date: 7.OCT.2022 20:29:08

Band 5_10 MHz_Low_16QAM_RB50#0




Date: 7.OCT.2022 20:29:16

Band 5_10 MHz_High_QPSK_RB50#0




Date: 7.OCT.2022 20:29:25

Band 5_10 MHz_High_16QAM_RB50#0




Date: 7.OCT.2022 20:29:33

Band 12_1.4 MHz_Low_QPSK_RB6#0




Date: 7.OCT.2022 20:29:46

Band 12_1.4 MHz_Low_16QAM_RB6#0




Date: 7.OCT.2022 20:29:52

Band 12_1.4 MHz_High_QPSK_RB6#0




Date: 7.OCT.2022 20:29:59

Band 12_1.4 MHz_High_16QAM_RB6#0




Date: 7.OCT.2022 20:30:05

Band 12_3 MHz_Low_QPSK_RB15#0




Date: 7.OCT.2022 20:30:52

Band 12_3 MHz_Low_16QAM_RB15#0




Date: 7.OCT.2022 20:30:59

Band 12_3 MHz_High_QPSK_RB15#0




Date: 7.OCT.2022 20:31:06

Band 12_3 MHz_High_16QAM_RB15#0




Date: 7.OCT.2022 20:31:12

Band 12_5 MHz_Low_QPSK_RB25#0




Date: 7.OCT.2022 20:33:39

Band 12_5 MHz_Low_16QAM_RB25#0




Date: 7.OCT.2022 20:33:46

Band 12_5 MHz_High_QPSK_RB25#0




Date: 7.OCT.2022 20:33:53

Band 12_5 MHz_High_16QAM_RB25#0




Date: 7.OCT.2022 20:34:00

Band 12_10 MHz_Low_QPSK_RB50#0




Date: 7.OCT.2022 20:36:25

Band 12_10 MHz_Low_16QAM_RB50#0




Date: 7.OCT.2022 20:36:33

Band 12_10 MHz_High_QPSK_RB50#0




Date: 7.OCT.2022 20:36:41

Band 12_10 MHz_High_16QAM_RB50#0




Date: 7.OCT.2022 20:36:48

Band 13_5 MHz_Low_QPSK_RB25#0




Date: 7.OCT.2022 20:37:01

Band 13_5 MHz_Low_16QAM_RB25#0




Date: 7.OCT.2022 20:37:08

Band 13_5 MHz_High_QPSK_RB25#0




Date: 7.OCT.2022 20:37:15

Band 13_5 MHz_High_16QAM_RB25#0




Date: 7.OCT.2022 20:37:22

Band 13_10 MHz_Low_QPSK_RB50#0




Date: 20.OCT.2022 13:48:43

Band 13_10 MHz_Low_16QAM_RB50#0




Date: 20.OCT.2022 13:48:14

Band 13_10 MHz_High_QPSK_RB50#0




Date: 20.OCT.2022 13:47:45

Band 13_10 MHz_High_16QAM_RB50#0




Date: 20.OCT.2022 13:46:48

Band 25_1.4 MHz_Low_QPSK_RB6#0




Date: 9.OCT.2022 15:08:10

Band 25_1.4 MHz_Low_16QAM_RB6#0




Date: 9.OCT.2022 15:08:17

Band 25_1.4 MHz_High_QPSK_RB6#0




Date: 9.OCT.2022 15:08:25

Band 25_1.4 MHz_High_16QAM_RB6#0




Date: 9.OCT.2022 15:08:33

Band 25_3 MHz_Low_QPSK_RB15#0




Date: 9.OCT.2022 15:09:12

Band 25_3 MHz_Low_16QAM_RB15#0




Date: 9.OCT.2022 15:09:19

Band 25_3 MHz_High_QPSK_RB15#0




Date: 9.OCT.2022 15:09:28

Band 25_3 MHz_High_16QAM_RB15#0




Date: 9.OCT.2022 15:09:37

Band 25_5 MHz_Low_QPSK_RB25#0




Date: 9.OCT.2022 15:10:24

Band 25_5 MHz_Low_16QAM_RB25#0




Date: 9.OCT.2022 15:10:31

Band 25_5 MHz_High_QPSK_RB25#0




Date: 9.OCT.2022 15:10:40

Band 25_5 MHz_High_16QAM_RB25#0




Date: 9.OCT.2022 15:10:49

Band 25_10 MHz_Low_QPSK_RB50#0




Date: 9.OCT.2022 15:11:37

Band 25_10 MHz_Low_16QAM_RB50#0




Date: 9.OCT.2022 15:11:45

Band 25_10 MHz_High_QPSK_RB50#0




Date: 9.OCT.2022 15:11:55

Band 25_10 MHz_High_16QAM_RB50#0




Date: 9.OCT.2022 15:12:04

Band 25_15 MHz_Low_QPSK_RB75#0




Date: 9.OCT.2022 15:12:44

Band 25_15 MHz_Low_16QAM_RB75#0




Date: 9.OCT.2022 15:12:52

Band 25_15 MHz_High_QPSK_RB75#0




Date: 9.OCT.2022 15:13:01

Band 25_15 MHz_High_16QAM_RB75#0




Date: 9.OCT.2022 15:13:09

Band 25_20 MHz_Low_QPSK_RB100#0




Date: 9.OCT.2022 15:13:49

Band 25_20 MHz_Low_16QAM_RB100#0




Date: 9.OCT.2022 15:13:57

Band 25_20 MHz_High_QPSK_RB100#0




Date: 9.OCT.2022 15:14:06

Band 25_20 MHz_High_16QAM_RB100#0




Date: 9.OCT.2022 15:14:14

Band 41_5 MHz_Low_QPSK_RB25#0




Date: 9.OCT.2022 16:45:32

Band 41_5 MHz_Low_16QAM_RB25#0




Date: 9.OCT.2022 16:44:45

Band 41_5 MHz_High_QPSK_RB25#0




Date: 9.OCT.2022 16:31:35

Band 41_5 MHz_High_16QAM_RB25#0




Date: 9.OCT.2022 16:31:58

Band 41_10 MHz_Low_QPSK_RB50#0




Date: 9.OCT.2022 16:34:12

Band 41_10 MHz_Low_16QAM_RB50#0




Date: 9.OCT.2022 16:34:43

Band 41_10 MHz_High_QPSK_RB50#0




Date: 9.OCT.2022 16:35:16

Band 41_10 MHz_High_16QAM_RB50#0




Date: 9.OCT.2022 16:35:39

Band 41_15 MHz_Low_QPSK_RB75#0




Date: 9.OCT.2022 16:37:41

Band 41_15 MHz_Low_16QAM_RB75#0




Date: 9.OCT.2022 16:37:02

Band 41_15 MHz_High_QPSK_RB75#0




Date: 9.OCT.2022 16:38:03

Band 41_15 MHz_High_16QAM_RB75#0




Date: 9.OCT.2022 16:38:27

Band 41_20 MHz_Low_QPSK_RB100#0




Date: 9.OCT.2022 16:41:02

Band 41_20 MHz_Low_16QAM_RB100#0




Date: 9.OCT.2022 16:41:30

Band 41_20 MHz_High_QPSK_RB100#0




Date: 9.OCT.2022 16:42:06

Band 41_20 MHz_High_16QAM_RB100#0




Date: 9.OCT.2022 16:42:21

Band 66_1.4 MHz_Low_QPSK_RB6#0




Date: 8.OCT.2022 10:46:45

Band 66_1.4 MHz_Low_16QAM_RB6#0




Date: 8.OCT.2022 10:46:52

Band 66_1.4 MHz_High_QPSK_RB6#0




Date: 8.OCT.2022 10:46:59

Band 66_1.4 MHz_High_16QAM_RB6#0




Date: 8.OCT.2022 10:47:06

Band 66_3 MHz_Low_QPSK_RB15#0




Date: 8.OCT.2022 10:47:48

Band 66_3 MHz_Low_16QAM_RB15#0




Date: 8.OCT.2022 10:47:54

Band 66_3 MHz_High_QPSK_RB15#0




Date: 8.OCT.2022 10:48:02

Band 66_3 MHz_High_16QAM_RB15#0




Date: 8.OCT.2022 10:48:08

Band 66_5 MHz_Low_QPSK_RB25#0




Date: 8.OCT.2022 10:48:51

Band 66_5 MHz_Low_16QAM_RB25#0




Date: 8.OCT.2022 10:48:58

Band 66_5 MHz_High_QPSK_RB25#0




Date: 8.OCT.2022 10:49:06

Band 66_5 MHz_High_16QAM_RB25#0




Date: 8.OCT.2022 10:49:14

Band 66_10 MHz_Low_QPSK_RB50#0




Date: 8.OCT.2022 10:49:57

Band 66_10 MHz_Low_16QAM_RB50#0




Date: 8.OCT.2022 10:50:05

Band 66_10 MHz_High_QPSK_RB50#0




Date: 8.OCT.2022 10:50:14

Band 66_10 MHz_High_16QAM_RB50#0




Date: 8.OCT.2022 10:50:22

Band 66_15 MHz_Low_QPSK_RB75#0




Date: 8.OCT.2022 10:51:05

Band 66_15 MHz_Low_16QAM_RB75#0




Date: 8.OCT.2022 10:51:12

Band 66_15 MHz_High_QPSK_RB75#0




Date: 8.OCT.2022 10:51:20

Band 66_15 MHz_High_16QAM_RB75#0




Date: 8.OCT.2022 10:51:26

Band 66_20 MHz_Low_QPSK_RB100#0




Date: 8.OCT.2022 10:52:13

Band 66_20 MHz_Low_16QAM_RB100#0




Date: 8.OCT.2022 10:52:20

Band 66_20 MHz_High_QPSK_RB100#0



Date: 8.OCT.2022 10:52:28

Band 66_20 MHz_High_16QAM_RB100#0



Date: 8.OCT.2022 10:52:35