

XKYWAND1001 Labeling and Location





Label is permanently attached to the device with adhesive and is resistant against wear.

Base Material: PET

Adhesive: 3M part number 3M 467MP 0.05mm