	Report No: R3196 Issue No: 1	FCC ID: X09-DOOR-1001 IC: 8906A-DOOR1001	
	Test No: T4610	Test Photos	Page: 1 of 3



dB Technology
 ----- (Cambridge Ltd.) -----
 EMC Testing EMC Consultancy EMC Training

23, Headington Drive,
 Cambridge,
 CB1 9HE
 Tel : 01954 251974 (test site)
 or : 01223 241140 (accounts)
 Fax : 01954 251907
 web : www.dbtechnology.co.uk
 email: mail@dbtechnology.co.uk

REPORT ON ELECTROMAGNETIC COMPATIBILITY TESTS

Performed at:
TWENTY PENCE TEST SITE

**Twenty Pence Road,
 Cottenham,
 Cambridge
 U.K.
 CB24 8PS**

on

Sureflap Ltd

Sureflap

dated


18th February 2013

Document History

Issue	Date	Affected page(s)	Description of modifications	Revised by	Approved by
1	18/02/13		Initial release		


Based on report template:
 v090319

*This report shall not be reproduced except in full, without the written approval of:
 dB Technology (Cambridge) Ltd.*

	Report No: R3196 Issue No: 1	FCC ID: X09-DOOR-1001 IC: 8906A-DOOR1001	
	Test No: T4610	Test Photos	Page: 2 of 3

Contents

<i>Photograph 1 Radiated Emissions - below 30MHz</i>	3
<i>Photograph 2 Radiated Emissions - above 30MHz</i>	3

	Report No: R3196	FCC ID: X09-DOOR-1001	
	Issue No: 1	IC: 8906A-DOOR1001	
Test No: T4610	Test Photos		Page: 3 of 3



Photograph 1 Radiated Emissions - below 30MHz



Photograph 2 Radiated Emissions - above 30MHz

*This report shall not be reproduced except in full, without the written approval of:
dB Technology (Cambridge) Ltd.*