

Date: January 3, 2018

Federal Communications Commission Authorization and Evaluation Division Columbia, MD 21046

Subject: Request to change in Identification

To Whom It May Concern:

This application for Change of Identification request a new FCC ID as stipulated in 47CFR 2.933(b) for presently authorized equipment.

This application by **TRENDNET**, **Inc.** will establish a new FCC ID under FCC ID: **XU8TBW108UB** for the purpose of marketing.

The original grant to Edimax Technology Co Ltd, FCC ID: NDD9576111602 will remain in effect.

Per 2.933(b)

- (1) The original identification is FCC ID: NDD9576111602
- (2) The original grant date is 06/22/2016
- (3) The equipment is electrically and functionally identical. Only the model name, trade name, and FCC ID number are different.
- (4) The original test results are applicable and representative of this changed device

Sincerely,

Applicant : TRENDNET, Inc.

Address : 20675 Manhattan Place Torrance California 90501 United States

Signature :

Name and Job Title. : Wen Tsai, Sr. Product Manager

E-mail : w.tsai@trendnet.com
Tel. : 310-961-5500 ex 5474