

TRENDNET, INC.

20675 Manhattan Place, Torrance, CA 90501 USA

Attention: Application Examiner/ Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Reference: FCC ID: XU8TEW738-739

To The Commission:

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by TRENDNET, INC. will establish a new FCC ID under TRENDNET, INC. grantee code for purpose of marketing. The original grant to FCC ID: SCDOW141000001. will remain in effect.

An authorization letter by LanReady Technologies Inc. is attached.

Per 2.933(b)

1. The original identification is SCDOW141000001
2. The original grant date is 08/09/2013
3. The equipment is electrically identical. Only the model name, trade name, and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

Sincerely,



TRENDNET, INC.

Name: Wen Tsai

Title: Sr. Product Manager

Date: 09/24/2015