LanReady Technologies Inc. 3F, No.116, Sinhu 2nd Rd., Neihu District, Taipei City 114, Taiwan (R.O.C.)

To: TRENDNET, INC.

20675 Manhattan Place, Torrance, CA 90501 USA

Re: Change of Identification Authorization

FCC ID: SCDOW141000001

Date: 09/24/2015

To Whom It May Concern:

This letter grants authorization for representatives of TRENDNET, INC. to apply to the FCC for a change in identification as specified under 47CFR2.933 of the FCC rules. This authorization applies to LanReady Technologies Inc. (Product description: AP Router), FCC ID SCDOW141000001, granted on 08/09/2013. The equipment is electrically identical the only change being the labels on the device. The original test results continue to be representative of and applicable to the changed equipment.

Sincerely,

Spencer Chen /CTO

LanReady Technologies Inc.