## TRENDnet, Inc.

Federal Communications Commission Authorization and Evaluation Division 1435 Oakland Mills Road Columbia, MD 21046

Date:

SUBJECT: FCC Application for XU8TPL310AP

To Whom It May Concern:

We, the undersigned, IN HOUSE BPL AND CARRIER CURRENT SYSTEMS: the verification procedure has been applied for in house BPL and carrier current systems. For in-house and access BPL systems, the measurement guidelines can be found in Appendix C of Report and Order FCC 04-245 (Measurement Guidelines for Broadband Over Power Line (BPL) Devices Or Carrier Current Systems (CCS) and Certification Requirements For Access BPL Devices).

Regards,

Signature

Name/title: Wen Tsai / Sr. Product Manager

**Company Name: TRENDnet, Inc.** 

Address: 20675 Manhattan Place Torrance, CA 90501 United States

Tel: (310) 961-5500 5474 Fax: (310) 961-5511

e-mail address: w.tsai@trendnet.com