

USB-C

STATUS



ERROR



READY



TRAXXAS®

6-CELL NiMH 2-CELL LiPo  
7-CELL 3-CELL

PEAK DETECTING BALANCE CHARGER

iD



4AMP

USB-C

READ ALL INSTRUCTIONS BEFORE CHARGING

Plug charger into USB-C power FIRST,  
then connect the iD battery to charge

Do not charge battery unattended

Input: 5-20V  $\equiv \equiv \equiv$  3A

NiMH: Output: 10.75 V  $\equiv \equiv \equiv$  4A

LiPo: Output: 12.6 V  $\equiv \equiv \equiv$  4A

FCC ID: XVE-TRX1042 MODEL NO. 2985

IC: 8668A-TRX1042 [Traxxas.com/pat](http://Traxxas.com/pat)



FC

CE



BC



020334017765-10-2023

HKA23081-R00