

No. 53-11, Dingfu, Linkou, Dist., New Taipei City244, Taiwan APPENDIX B-Page 1 of 3 Tel: +886 2 26099301

Tel: +886 2 26099301 Fax: +886 2 26099303

B.1 Conducted Emission Measurement



FRONT VIEW



BACK VIEW

File Number: C1M1803257

Report Number: EM-F180128


This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX B-Page 2 of 3 Tel: +886 2 26099301 Fax: +886 2 26099303

B.2 Radiated Measurement at Chamber

Frequency Below to 1GHz




File Number: C1M1803257Report Number: EM-F180128This test report may be reproduced in full only. The document may only be updated by Audix Technology
Corp. personnel. Any changes will be noted in the Document History section of the report.



APPENDIX B-Page 3 of 3

Tel: +886 2 26099301 *Fax:* +886 2 26099303

B.3 RF Conducted Measurement



File Number: C1M1803257

Report Number: EM-F180128

This test report may be reproduced in full only. The document may only be updated by Audix Technology Corp. personnel. Any changes will be noted in the Document History section of the report.