

From  
CM-CI1/EHW-CN

Our Reference  
Yang Rui

Tel  
+86(512)67673454


Hildesheim  
12 April 2017

Device 52R0  
Topic Device Internal Pictures  
Description

### 1.1 Bluetooth module



### 1.2 Bluetooth module inside



From  
CM-C11/EHW-CN

Our Reference  
Yang Rui

Tel  
+86(512)67673454


Hildesheim  
12 April 2017

Report  
Issue 52R0  
Topic Device Internal Pictures

### **1.3 Mainboard Top View**



### **1.4 Mainboard Bottom View**





From  
CM-C11/EHW-CN


Our Reference  
Yang Rui

Tel  
+86(512)67673454


Hildesheim  
12 April 2017

Report  
Issue 52R0  
Topic Device Internal Pictures

### **1.5 Housing**



### **1.6 Upper cover**



From  
CM-C11/EHW-CN

Our Reference  
Yang Rui

Tel  
+86(512)67673454


Hildesheim  
12 April 2017

Report


Issue 52R0

Topic Device Internal Pictures

### **1.7 Fascia Board Bottom Side**



### **1.8 Fascia Board Top Side**







From  
CM-C11/EHW-CN

Our Reference  
Yang Rui

Tel  
+86(512)67673454

Hildesheim  
12 April 2017

Report


Issue 52R0

Topic Device Internal Pictures

### **1.9 Fascia Back side**



### **1.10 Display backside light guide**



From  
CM-C11/EHW-CN

Our Reference  
Yang Rui

Tel  
+86(512)67673454

Hildesheim  
12 April 2017

Report  
Issue 52R0  
Topic Device Internal Pictures

### ***1.11 Display cover light guide***



From  
CM-C11/EHW-CN

Our Reference  
Yang Rui

Tel  
+86(512)67673454

Hildesheim  
12 April 2017

Report  
Issue 52R0  
Topic Device Internal Pictures

