


page 1 of 8

# ANNEX A INTERNAL PHOTOS



113093\_EUT30.JPG: ALPS eavluation board, top view

Test Report No.: F113093E2 Annex A Order No.: 11-113093



page 2 of 8

# ANNEX A INTERNAL PHOTOS



113093\_EUT31.JPG: ALPS eavluation board, bottom view

 Examiner:
 Manuel BASTERT
 Test Report No.:
 F113093E2 Annex A

 Date of issue:
 26 October 2011
 Order No.:
 F113093E2 Annex A

 11-113093
 11-113093



page 3 of 8

# ANNEX A INTERNAL PHOTOS



113093\_EUT23.JPG: Switch PCB, rear view


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F113093E2 Annex A

 Date of issue:
 26 October 2011
 Order No.:
 F113093E2 Annex A

 11-113093
 11-113093



# ANNEX A INTERNAL PHOTOS



113093\_EUT25.JPG: Switch PCB, front view

Examiner: Manuel BASTERT Date of issue: 26 October 2011 Test Report No.: F113093E2 Annex A Order No.: 11-113093



# ANNEX A INTERNAL PHOTOS




113093\_EUT24.JPG: Switch PCB, detail view to Bluetooth unit (shielded)

Test Report No.: F113093E2 Annex A Order No.: 11-113093



page 6 of 8

# ANNEX A INTERNAL PHOTOS



113093\_EUT33.JPG: Switch PCB, detail view to Bluetooth unit (unshielded)


 Examiner:
 Manuel BASTERT
 Test Report No.:
 F113093E2 Annex A

 Date of issue:
 26 October 2011
 Order No.:
 11-113093



page 7 of 8

# ANNEX A INTERNAL PHOTOS




113093\_EUT27.JPG: Switch PCB, detail view to temporary antenna connector

Test Report No.: F113093E2 Annex A Order No.: 11-113093



page 8 of 8

# ANNEX A INTERNAL PHOTOS



113093\_EUT15.JPG: Switch PCB, detail view to integrated antenna

Test Report No.: F113093E2 Annex A Order No.: 11-113093