


**Annex A    Test setup photos**



161612\_DFS0.jpg: Test setup

**Annex A Test setup photos**


**External photos of dedicated host**



161612\_DFS\_M1.jpg: FL WLAN 2101, 3D view 1

Due to test sample status, the model number WLAN 1100 does not correspond to the containing EUT.


**Annex A Test setup photos**



161612\_DFS\_M2.jpg: FL WLAN 2101, 3D view 2


**Annex A Test setup photos**

**Internal photos of dedicated host**




161612\_DFS5.jpg: FL WLAN 2101, Main PCB, top view

Annex A Test setup photos



161612\_DFS6.jpg: FL WLAN 2101, Main PCB, top view, WLAN module removed

**Annex A Test setup photos**



161612\_DFS7.jpg: FL WLAN 2101, Main PCB, bottom view