

# **SETUP PHOTOS EXHIBIT**

**Report Number:** R13573691-EP1

**Applicant :** Crown Equipment Corporation  
44 South Washington Street  
New Bremen, OH 45869 USA

**Model :** HD4010

**Contains FCC ID :** YGP4000-01

**Contains IC :** 9016A-HD4000A

**EUT Description :** HD4010 Truck Charger

**Test Standard(s) :** FCC 47 CFR PART 15 SUBPART C  
ISED RSS-247 ISSUE 2  
ISED RSS-GEN ISSUE 5+A1

**Date Of Issue:**  
2023-02-03

**Prepared by:**  
UL LLC  
12 Laboratory Dr.  
Research Triangle Park, NC 27709 U.S.A.  
TEL: (919) 549-1400




## REPORT REVISION HISTORY

| Rev. | Issue Date | Revisions               | Revised By      |
|------|------------|-------------------------|-----------------|
| 1    | 2020-11-19 | Initial Issue           | Brian T. Kiewra |
| 2    | 2023-02-03 | Revised EUT description | Brian T. Kiewra |

## TABLE OF CONTENTS


|                               |   |
|-------------------------------|---|
| REPORT REVISION HISTORY ..... | 2 |
| TABLE OF CONTENTS .....       | 3 |
| 1. SETUP DIAGRAMS .....       | 4 |
| 2. SETUP PHOTOS .....         | 5 |
| END OF TEST REPORT .....      | 9 |


## 1. SETUP DIAGRAMS




## 2. SETUP PHOTOS

### RADIATED SPURIOUS EMISSIONS






RADIATED SPURIOUS PHOTO (>1GHz)







RADIATED SPURIOUS PHOTO (X Orientation)



RADIATED SPURIOUS PHOTO (Y Orientation)







**END OF EXHIBIT**