



Please refer to following plots:




Date: 18.JUL.2021 18:29:47




Date: 13.AUG.2021 01:25:41

### Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 14.AUG.2021 17:58:00

### Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 14.AUG.2021 17:56:35

### Band 2\_3 MHz\_Low\_QPSK\_RB15#0




Date: 18.JUL.2021 17:45:42

### Band 2\_3 MHz\_Low\_16QAM\_RB15#0




Date: 18.JUL.2021 17:45:59

### Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 18.JUL.2021 17:46:19

### Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 18.JUL.2021 17:46:36

### Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 22.JUL.2021 01:24:47

### Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 18.JUL.2021 17:47:17

### Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 21.JUL.2021 03:31:59

### Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 22.JUL.2021 01:27:19

### Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 18.JUL.2021 17:48:20

### Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 18.JUL.2021 17:48:39

### Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 18.JUL.2021 17:48:59


### Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 18.JUL.2021 17:49:18




### Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 21.JUL.2021 03:34:04

### Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 18.JUL.2021 17:50:12

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 22.JUL.2021 01:30:56

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 22.JUL.2021 01:32:17

### Band 2\_20 MHz\_Low\_QPSK\_RB100#0




Date: 18.JUL.2021 17:51:31

### Band 2\_20 MHz\_Low\_16QAM\_RB100#0




Date: 18.JUL.2021 17:51:55

### Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 18.JUL.2021 17:52:19

### Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 18.JUL.2021 17:52:42

### Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 18.JUL.2021 17:53:06

### Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 13.AUG.2021 01:34:12

### Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 18.JUL.2021 17:53:50

### Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 18.JUL.2021 17:54:07

### Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 18.JUL.2021 17:54:27

### Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 18.JUL.2021 17:54:44

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 18.JUL.2021 17:55:02


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 18.JUL.2021 17:55:22




### Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 18.JUL.2021 17:55:43

### Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 18.JUL.2021 17:56:03

### Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 18.JUL.2021 17:56:27

### Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 18.JUL.2021 17:56:47

### Band 4\_10 MHz\_Low\_QPSK\_RB50#0




Date: 18.JUL.2021 17:57:13

### Band 4\_10 MHz\_Low\_16QAM\_RB50#0




Date: 18.JUL.2021 17:57:32

### Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 18.JUL.2021 17:57:52

### Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 18.JUL.2021 17:58:14

### Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 22.JUL.2021 01:34:01

### Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 18.JUL.2021 17:59:05

### Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 18.JUL.2021 17:59:30

### Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 21.JUL.2021 03:44:08

### Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 18.JUL.2021 18:00:24

### Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 18.JUL.2021 18:00:51

### Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 18.JUL.2021 18:01:15


### Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 18.JUL.2021 18:01:39




### Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 13.AUG.2021 01:42:28

### Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 18.JUL.2021 18:02:16

### Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 21.JUL.2021 03:46:46

### Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 13.AUG.2021 01:43:29

### Band 5\_3 MHz\_Low\_QPSK\_RB15#0




Date: 18.JUL.2021 18:03:21

### Band 5\_3 MHz\_Low\_16QAM\_RB15#0




Date: 18.JUL.2021 18:03:38

### Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 18.JUL.2021 18:03:55

### Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 18.JUL.2021 18:04:12

### Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 22.JUL.2021 01:36:32

### Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 18.JUL.2021 18:04:50

### Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 22.JUL.2021 01:38:54

### Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 22.JUL.2021 01:39:37

### Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 18.JUL.2021 18:05:46

### Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 18.JUL.2021 18:06:05

### Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 18.JUL.2021 18:06:25


### Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 18.JUL.2021 18:06:44




### Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 22.JUL.2021 01:41:57

### Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 18.JUL.2021 18:07:25

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 22.JUL.2021 01:43:48

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 22.JUL.2021 01:45:10

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0




Date: 18.JUL.2021 18:08:22

### Band 7\_10 MHz\_Low\_16QAM\_RB50#0




Date: 18.JUL.2021 18:08:41

### Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 18.JUL.2021 18:09:01

### Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 18.JUL.2021 18:09:20

### Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 22.JUL.2021 01:47:11

### Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 18.JUL.2021 18:10:11

### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 22.JUL.2021 02:02:13

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 13.AUG.2021 01:51:25

### Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 13.AUG.2021 01:51:51

### Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 18.JUL.2021 18:11:57

### Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 21.JUL.2021 03:56:28


### Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 18.JUL.2021 18:12:44




### Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 18.JUL.2021 18:13:05

### Band 12\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 18.JUL.2021 18:13:25

### Band 12\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 18.JUL.2021 18:13:46

### Band 12\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 18.JUL.2021 18:14:05

### Band 12\_3 MHz\_Low\_QPSK\_RB15#0




Date: 18.JUL.2021 18:14:27

### Band 12\_3 MHz\_Low\_16QAM\_RB15#0




Date: 18.JUL.2021 18:14:47

### Band 12\_3 MHz\_High\_QPSK\_RB15#0




Date: 18.JUL.2021 18:15:05

### Band 12\_3 MHz\_High\_16QAM\_RB15#0




Date: 18.JUL.2021 18:15:21

### Band 12\_5 MHz\_Low\_QPSK\_RB25#0




Date: 21.JUL.2021 03:59:50

### Band 12\_5 MHz\_Low\_16QAM\_RB25#0




Date: 21.JUL.2021 04:00:07

### Band 12\_5 MHz\_High\_QPSK\_RB25#0




Date: 22.JUL.2021 02:08:02

### Band 12\_5 MHz\_High\_16QAM\_RB25#0




Date: 22.JUL.2021 02:08:39

### Band 12\_10 MHz\_Low\_QPSK\_RB50#0




Date: 18.JUL.2021 18:17:05

### Band 12\_10 MHz\_Low\_16QAM\_RB50#0




Date: 18.JUL.2021 18:17:24

### Band 12\_10 MHz\_High\_QPSK\_RB50#0



Date: 18.JUL.2021 18:17:44


### Band 12\_10 MHz\_High\_16QAM\_RB50#0



Date: 18.JUL.2021 18:18:03




### Band 17\_5 MHz\_Low\_QPSK\_RB25#0




Date: 22.JUL.2021 02:10:08

### Band 17\_5 MHz\_Low\_16QAM\_RB25#0




Date: 18.JUL.2021 18:18:44

### Band 17\_5 MHz\_High\_QPSK\_RB25#0




Date: 22.JUL.2021 02:12:36

### Band 17\_5 MHz\_High\_16QAM\_RB25#0




Date: 22.JUL.2021 02:11:53

### Band 17\_10 MHz\_Low\_QPSK\_RB50#0




Date: 18.JUL.2021 18:19:44

### Band 17\_10 MHz\_Low\_16QAM\_RB50#0




Date: 18.JUL.2021 18:20:03

### Band 17\_10 MHz\_High\_QPSK\_RB50#0




Date: 18.JUL.2021 18:20:23

### Band 17\_10 MHz\_High\_16QAM\_RB50#0




Date: 18.JUL.2021 18:20:42

### Band 66\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 22.JUL.2021 01:18:09

### Band 66\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 21.JUL.2021 03:15:01

### Band 66\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 21.JUL.2021 03:15:19

### Band 66\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 21.JUL.2021 03:15:39

### Band 66\_3 MHz\_Low\_QPSK\_RB15#0




Date: 21.JUL.2021 03:16:11

### Band 66\_3 MHz\_Low\_16QAM\_RB15#0




Date: 21.JUL.2021 03:16:27

### Band 66\_3 MHz\_High\_QPSK\_RB15#0



Date: 21.JUL.2021 03:16:45


### Band 66\_3 MHz\_High\_16QAM\_RB15#0



Date: 21.JUL.2021 03:17:05




### Band 66\_5 MHz\_Low\_QPSK\_RB25#0




Date: 14.AUG.2021 18:05:11

### Band 66\_5 MHz\_Low\_16QAM\_RB25#0




Date: 21.JUL.2021 03:17:45

### Band 66\_5 MHz\_High\_QPSK\_RB25#0




Date: 14.AUG.2021 18:06:11

### Band 66\_5 MHz\_High\_16QAM\_RB25#0




Date: 14.AUG.2021 18:07:01

### Band 66\_10 MHz\_Low\_QPSK\_RB50#0




Date: 21.JUL.2021 03:18:48

### Band 66\_10 MHz\_Low\_16QAM\_RB50#0




Date: 21.JUL.2021 03:19:10

### Band 66\_10 MHz\_High\_QPSK\_RB50#0




Date: 21.JUL.2021 03:19:30

### Band 66\_10 MHz\_High\_16QAM\_RB50#0




Date: 21.JUL.2021 03:19:52

### Band 66\_15 MHz\_Low\_QPSK\_RB75#0




Date: 21.JUL.2021 03:20:19

### Band 66\_15 MHz\_Low\_16QAM\_RB75#0




Date: 21.JUL.2021 03:20:46

### Band 66\_15 MHz\_High\_QPSK\_RB75#0




Date: 14.AUG.2021 18:08:47

### Band 66\_15 MHz\_High\_16QAM\_RB75#0




Date: 14.AUG.2021 18:08:47

### Band 66\_20 MHz\_Low\_QPSK\_RB100#0




Date: 21.JUL.2021 03:22:04

### Band 66\_20 MHz\_Low\_16QAM\_RB100#0




Date: 21.JUL.2021 03:22:30

### Band 66\_20 MHz\_High\_QPSK\_RB100#0



Date: 21.JUL.2021 03:22:54

### Band 66\_20 MHz\_High\_16QAM\_RB100#0



Date: 21.JUL.2021 03:23:21