



Please refer to following plots:

Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 3.MAR.2021 14:29:15

Band 2\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 3.MAR.2021 14:29:44

Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 3.MAR.2021 14:30:07

Band 2\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 3.MAR.2021 14:30:33

Band 2\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 3.MAR.2021 14:31:01

Band 2\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 3.MAR.2021 14:31:24

Band 2\_3 MHz\_Low\_QPSK\_RB15#0



Date: 3.MAR.2021 14:31:47


Band 2\_3 MHz\_Low\_16QAM\_RB15#0



Date: 3.MAR.2021 14:32:15




Band 2\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 3.MAR.2021 14:32:41

Band 2\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 3.MAR.2021 14:33:07

Band 2\_3 MHz\_High\_QPSK\_RB15#0




Date: 3.MAR.2021 14:33:29

Band 2\_3 MHz\_High\_16QAM\_RB15#0




Date: 3.MAR.2021 14:33:52

Band 2\_5 MHz\_Low\_QPSK\_RB25#0




Date: 3.MAR.2021 14:34:21

Band 2\_5 MHz\_Low\_16QAM\_RB25#0




Date: 3.MAR.2021 14:34:46

Band 2\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 3.MAR.2021 14:35:15


Band 2\_5 MHz\_Middle\_16QAM\_RB25#0



Date: 3.MAR.2021 14:35:44




Band 2\_5 MHz\_High\_QPSK\_RB25#0




Date: 3.MAR.2021 14:36:09

Band 2\_5 MHz\_High\_16QAM\_RB25#0




Date: 3.MAR.2021 14:36:45

Band 2\_10 MHz\_Low\_QPSK\_RB50#0




Date: 3.MAR.2021 14:37:16

Band 2\_10 MHz\_Low\_16QAM\_RB50#0




Date: 3.MAR.2021 14:37:50

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 3.MAR.2021 14:38:31

Band 2\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 3.MAR.2021 14:39:11

Band 2\_10 MHz\_High\_QPSK\_RB50#0



Date: 3.MAR.2021 14:39:51


Band 2\_10 MHz\_High\_16QAM\_RB50#0



Date: 3.MAR.2021 14:40:23




Band 2\_15 MHz\_Low\_QPSK\_RB75#0




Date: 3.MAR.2021 14:41:01

Band 2\_15 MHz\_Low\_16QAM\_RB75#0




Date: 3.MAR.2021 14:41:46

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0




Date: 3.MAR.2021 14:42:31

Band 2\_15 MHz\_Middle\_16QAM\_RB75#0




Date: 3.MAR.2021 14:43:16

### Band 2\_15 MHz\_High\_QPSK\_RB75#0




Date: 3.MAR.2021 14:44:04

### Band 2\_15 MHz\_High\_16QAM\_RB75#0




Date: 3.MAR.2021 14:44:49

Band 2\_20 MHz\_Low\_QPSK\_RB100#0



Date: 3.MAR.2021 14:45:31


Band 2\_20 MHz\_Low\_16QAM\_RB100#0



Date: 3.MAR.2021 14:46:09




Band 2\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 3.MAR.2021 14:46:57

Band 2\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 3.MAR.2021 14:47:45

Band 2\_20 MHz\_High\_QPSK\_RB100#0




Date: 3.MAR.2021 14:48:29

Band 2\_20 MHz\_High\_16QAM\_RB100#0




Date: 3.MAR.2021 14:49:07

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 3.MAR.2021 15:50:51

Band 4\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 3.MAR.2021 15:51:17

Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0



Date: 3.MAR.2021 15:51:44


Band 4\_1.4 MHz\_Middle\_16QAM\_RB6#0



Date: 3.MAR.2021 15:52:07




Band 4\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 3.MAR.2021 15:52:36

Band 4\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 3.MAR.2021 15:52:58

Band 4\_3 MHz\_Low\_QPSK\_RB15#0




Date: 3.MAR.2021 15:53:21

Band 4\_3 MHz\_Low\_16QAM\_RB15#0




Date: 3.MAR.2021 15:53:46

### Band 4\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 3.MAR.2021 15:54:09

### Band 4\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 3.MAR.2021 15:54:31

### Band 4\_3 MHz\_High\_QPSK\_RB15#0



Date: 3.MAR.2021 15:54:57


### Band 4\_3 MHz\_High\_16QAM\_RB15#0



Date: 3.MAR.2021 15:55:20




Band 4\_5 MHz\_Low\_QPSK\_RB25#0




Date: 3.MAR.2021 15:55:42

Band 4\_5 MHz\_Low\_16QAM\_RB25#0




Date: 3.MAR.2021 15:56:35

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 3.MAR.2021 15:57:04

Band 4\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 3.MAR.2021 15:57:30

Band 4\_5 MHz\_High\_QPSK\_RB25#0




Date: 3.MAR.2021 15:57:55

Band 4\_5 MHz\_High\_16QAM\_RB25#0




Date: 3.MAR.2021 15:58:30

Band 4\_10 MHz\_Low\_QPSK\_RB50#0



Date: 3.MAR.2021 15:59:01


Band 4\_10 MHz\_Low\_16QAM\_RB50#0



Date: 3.MAR.2021 15:59:32




Band 4\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 3.MAR.2021 16:00:07

Band 4\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 3.MAR.2021 16:00:41

Band 4\_10 MHz\_High\_QPSK\_RB50#0




Date: 3.MAR.2021 16:01:15

Band 4\_10 MHz\_High\_16QAM\_RB50#0




Date: 3.MAR.2021 16:01:59

Band 4\_15 MHz\_Low\_QPSK\_RB75#0




Date: 3.MAR.2021 16:02:40

Band 4\_15 MHz\_Low\_16QAM\_RB75#0




Date: 3.MAR.2021 16:03:22

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0



Date: 3.MAR.2021 16:04:07


Band 4\_15 MHz\_Middle\_16QAM\_RB75#0



Date: 3.MAR.2021 16:04:48




Band 4\_15 MHz\_High\_QPSK\_RB75#0




Date: 3.MAR.2021 16:05:21

Band 4\_15 MHz\_High\_16QAM\_RB75#0




Date: 3.MAR.2021 16:06:06

Band 4\_20 MHz\_Low\_QPSK\_RB100#0




Date: 3.MAR.2021 16:06:41

Band 4\_20 MHz\_Low\_16QAM\_RB100#0




Date: 3.MAR.2021 16:07:21

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 3.MAR.2021 16:08:02

Band 4\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 3.MAR.2021 16:08:50

Band 4\_20 MHz\_High\_QPSK\_RB100#0



Date: 3.MAR.2021 16:09:25


Band 4\_20 MHz\_High\_16QAM\_RB100#0



Date: 3.MAR.2021 16:09:57




Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 4.MAR.2021 09:41:49

Band 5\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 4.MAR.2021 09:42:11

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 4.MAR.2021 09:42:32

Band 5\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 4.MAR.2021 09:42:54

Band 5\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 4.MAR.2021 09:43:12

Band 5\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 4.MAR.2021 09:43:35

Band 5\_3 MHz\_Low\_QPSK\_RB15#0



Date: 4.MAR.2021 09:44:00


Band 5\_3 MHz\_Low\_16QAM\_RB15#0



Date: 4.MAR.2021 09:44:26




Band 5\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 4.MAR.2021 09:44:58

Band 5\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 4.MAR.2021 09:45:21

Band 5\_3 MHz\_High\_QPSK\_RB15#0




Date: 26.MAR.2021 17:57:02

Band 5\_3 MHz\_High\_16QAM\_RB15#0




Date: 4.MAR.2021 09:46:16

Band 5\_5 MHz\_Low\_QPSK\_RB25#0




Date: 4.MAR.2021 09:46:51

Band 5\_5 MHz\_Low\_16QAM\_RB25#0




Date: 4.MAR.2021 09:47:23

### Band 5\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 4.MAR.2021 09:47:52


### Band 5\_5 MHz\_Middle\_16QAM\_RB25#0



Date: 4.MAR.2021 09:48:18




Band 5\_5 MHz\_High\_QPSK\_RB25#0




Date: 4.MAR.2021 09:48:44

Band 5\_5 MHz\_High\_16QAM\_RB25#0




Date: 4.MAR.2021 09:49:09

Band 5\_10 MHz\_Low\_QPSK\_RB50#0




Date: 4.MAR.2021 09:50:25

Band 5\_10 MHz\_Low\_16QAM\_RB50#0




Date: 4.MAR.2021 09:50:59

Band 5\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 4.MAR.2021 09:51:33

Band 5\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 4.MAR.2021 09:52:07

Band 5\_10 MHz\_High\_QPSK\_RB50#0



Date: 4.MAR.2021 09:52:48


Band 5\_10 MHz\_High\_16QAM\_RB50#0



Date: 4.MAR.2021 09:53:22




Band 7\_5 MHz\_Low\_QPSK\_RB25#0




Date: 4.MAR.2021 10:35:59

Band 7\_5 MHz\_Low\_16QAM\_RB25#0




Date: 4.MAR.2021 10:36:25

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 4.MAR.2021 10:36:54

Band 7\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 4.MAR.2021 10:37:22

### Band 7\_5 MHz\_High\_QPSK\_RB25#0




Date: 4.MAR.2021 10:37:51

### Band 7\_5 MHz\_High\_16QAM\_RB25#0




Date: 4.MAR.2021 10:38:23

### Band 7\_10 MHz\_Low\_QPSK\_RB50#0



Date: 4.MAR.2021 10:38:57


### Band 7\_10 MHz\_Low\_16QAM\_RB50#0



Date: 4.MAR.2021 10:39:28




Band 7\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 4.MAR.2021 10:39:59

Band 7\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 4.MAR.2021 10:40:37

Band 7\_10 MHz\_High\_QPSK\_RB50#0




Date: 4.MAR.2021 10:41:08

Band 7\_10 MHz\_High\_16QAM\_RB50#0




Date: 4.MAR.2021 10:41:39

Band 7\_15 MHz\_Low\_QPSK\_RB75#0




Date: 4.MAR.2021 10:42:24

Band 7\_15 MHz\_Low\_16QAM\_RB75#0




Date: 4.MAR.2021 10:43:12

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0



Date: 4.MAR.2021 10:43:51


Band 7\_15 MHz\_Middle\_16QAM\_RB75#0



Date: 4.MAR.2021 10:44:36




### Band 7\_15 MHz\_High\_QPSK\_RB75#0




Date: 4.MAR.2021 10:45:22

### Band 7\_15 MHz\_High\_16QAM\_RB75#0




Date: 4.MAR.2021 10:46:10

Band 7\_20 MHz\_Low\_QPSK\_RB100#0




Date: 4.MAR.2021 10:47:03

Band 7\_20 MHz\_Low\_16QAM\_RB100#0




Date: 4.MAR.2021 10:47:37

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 4.MAR.2021 10:48:31

Band 7\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 4.MAR.2021 10:49:13

Band 7\_20 MHz\_High\_QPSK\_RB100#0



Date: 4.MAR.2021 10:49:50


Band 7\_20 MHz\_High\_16QAM\_RB100#0



Date: 4.MAR.2021 10:50:24




Band 12\_1.4 MHz\_Low\_QPSK\_RB6#0




Date: 4.MAR.2021 11:33:58

Band 12\_1.4 MHz\_Low\_16QAM\_RB6#0




Date: 4.MAR.2021 11:34:21

Band 12\_1.4 MHz\_Middle\_QPSK\_RB6#0




Date: 4.MAR.2021 11:34:43

Band 12\_1.4 MHz\_Middle\_16QAM\_RB6#0




Date: 4.MAR.2021 11:35:06

Band 12\_1.4 MHz\_High\_QPSK\_RB6#0




Date: 4.MAR.2021 11:35:24

Band 12\_1.4 MHz\_High\_16QAM\_RB6#0




Date: 4.MAR.2021 11:35:53

Band 12\_3 MHz\_Low\_QPSK\_RB15#0



Date: 4.MAR.2021 11:36:17


Band 12\_3 MHz\_Low\_16QAM\_RB15#0



Date: 4.MAR.2021 11:36:39




Band 12\_3 MHz\_Middle\_QPSK\_RB15#0




Date: 4.MAR.2021 11:37:02

Band 12\_3 MHz\_Middle\_16QAM\_RB15#0




Date: 4.MAR.2021 11:37:31

Band 12\_3 MHz\_High\_QPSK\_RB15#0




Date: 4.MAR.2021 11:37:53

Band 12\_3 MHz\_High\_16QAM\_RB15#0




Date: 4.MAR.2021 11:38:16

Band 12\_5 MHz\_Low\_QPSK\_RB25#0




Date: 4.MAR.2021 11:38:42

Band 12\_5 MHz\_Low\_16QAM\_RB25#0




Date: 4.MAR.2021 11:39:17

Band 12\_5 MHz\_Middle\_QPSK\_RB25#0



Date: 4.MAR.2021 11:39:42

Band 12\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 4.MAR.2021 11:40:11








Band 12\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 4.MAR.2021 11:42:48

Band 12\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 4.MAR.2021 11:43:26

Band 12\_10 MHz\_High\_QPSK\_RB50#0



Date: 4.MAR.2021 11:43:50


Band 12\_10 MHz\_High\_16QAM\_RB50#0




Date: 4.MAR.2021 11:44:31



Please refer to following plots:




Date: 24.MAR.2021 15:25:39




Date: 24.MAR.2021 15:26:10

### Band 38\_5 MHz\_Middle\_QPSK\_RB25#0




Date: 24.MAR.2021 15:26:31

### Band 38\_5 MHz\_Middle\_16QAM\_RB25#0




Date: 24.MAR.2021 15:27:04

### Band 38\_5 MHz\_High\_QPSK\_RB25#0




Date: 24.MAR.2021 15:27:31

### Band 38\_5 MHz\_High\_16QAM\_RB25#0




Date: 24.MAR.2021 15:27:52

### Band 38\_10 MHz\_Low\_QPSK\_RB50#0



Date: 24.MAR.2021 15:28:20


### Band 38\_10 MHz\_Low\_16QAM\_RB50#0



Date: 24.MAR.2021 15:28:46




### Band 38\_10 MHz\_Middle\_QPSK\_RB50#0




Date: 24.MAR.2021 15:29:22

### Band 38\_10 MHz\_Middle\_16QAM\_RB50#0




Date: 24.MAR.2021 15:29:48

### Band 38\_10 MHz\_High\_QPSK\_RB50#0




Date: 24.MAR.2021 15:30:11

### Band 38\_10 MHz\_High\_16QAM\_RB50#0




Date: 24.MAR.2021 15:30:34

### Band 38\_15 MHz\_Low\_QPSK\_RB75#0



Date: 24.MAR.2021 15:31:02

### Band 38\_15 MHz\_Low\_16QAM\_RB75#0




Date: 24.MAR.2021 15:31:32






### Band 38\_15 MHz\_High\_QPSK\_RB75#0




Date: 24.MAR.2021 15:33:08

### Band 38\_15 MHz\_High\_16QAM\_RB75#0




Date: 24.MAR.2021 15:33:36

### Band 38\_20 MHz\_Low\_QPSK\_RB100#0




Date: 24.MAR.2021 15:34:06

### Band 38\_20 MHz\_Low\_16QAM\_RB100#0




Date: 24.MAR.2021 15:34:33

### Band 38\_20 MHz\_Middle\_QPSK\_RB100#0




Date: 24.MAR.2021 15:35:04

### Band 38\_20 MHz\_Middle\_16QAM\_RB100#0




Date: 24.MAR.2021 15:35:34

### Band 38\_20 MHz\_High\_QPSK\_RB100#0



Date: 24.MAR.2021 15:36:02

### Band 38\_20 MHz\_High\_16QAM\_RB100#0



Date: 24.MAR.2021 15:36:26