



Date: 9.MAY.2024 20:27:01




Date: 9.MAY.2024 20:27:10

Band25_10MHz_QPSK_26090_1RB#0_3000~2000_3000~20000

Band25_10MHz_16QAM_26090_1RB#0_0.009~0.000_3000~20000




Date: 9.MAY.2024 20:27:19




Date: 9.MAY.2024 20:27:28

Band25_10MHz_16QAM_26090_1RB#0_0.15~30_0.15~30


Band25_10MHz_16QAM_26090_1RB#0_30~1000_30~1000





Date: 9.MAY.2024 20:27:37





Date: 9.MAY.2024 20:27:45





Band25_10MHz_QPSK_26365_1RB#0_3000~2000_3000~20000

Band25_10MHz_16QAM_26365_1RB#0_0.009~0.15_0.009~0.15



Band25_10MHz_16QAM_26365_1RB#0_0.15~30_0.15~30

Band25_10MHz_16QAM_26365_1RB#0_30~1000_30~1000

